Certificate of Location of Government Corner

ID#: 852906 **Description:** 1/4 SEC COR 29 30 85 **Date Set:** 7/15/2013 **County:** Olmsted

Section: 29 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.4'
Post w/sign 2' east
This corner is located by GPS reference stations "Stucky A & B"

Corner History:

Gov't Notes: 40.00 Ch. set 1/4 sec post. BT's: 18" Elm S75°E 11 lks. 16" Lind N75°W 19 lks.

11-6-1874 T. Hunter (Book A, P.264 No.262) 1/4 post missing but both witness trees standing. Found remains of old stake at point indicated by field notes. Set new 1/4 post in its place properly marked. 16 west set stone 3x16x24 M&L 19.92 (1314.72') also set stake 6.30 chs (415.8') east of center 30.

2-5-1877 T. Hunter (Book A, P.306 No.301) found stake set P.264. 16 E set marked stake M&L 20.12-1/2 1328.25 to center section 29 stake set inters lines.

10-20-1971 County Surveyor, corner hopelessly lost. Deep gully in area fouled up by road carving on westerly directions. Found limestones at center 30 and 1/16 east of center 30 both exactly as recorded P.264 so corner could be replaced exactly. Line very rugged especially west 2/3 of 1/2 mile. Clear offset possible north 200' ± on west half while oposite on E 1/2. Should stay on or near line and brush and cut way there.

5-14-1977 Keith Ewers set a 1" pipe. Also, at the 1/16th corner west he found and used a stone monument. (Cert. No. 8530-2480)

3-4-1993 Vince Fangman found and used 1" pipe with cap. (Cert. No. 8530-3285 and 8530-3292)

12-6-1996 Vince Fangman found and used 1" pipe with cap. (Cert No. 8530-3914)

6-3-2004 County survey crew found 1" pipe w/cap up 0.5' in good condition. Set post w/sign 2' north.

9-6-2005 Vince Fangman found and used 1" pipe with cap. (Cert. No. 8530-6259)

9-25-2012 County survey crew found 3"x16" stone monument at 1/16th corner west.

10-3-2012 County survey crew found stone monument at the 1/16th corner north.

7-15-2013 Joel Thoreson, Olmsted County Surveyor, found 1" pipe with unmarked iron cap up 0.5 in good condition. The pipe is in line with fence remnants south. Survey crew removed 1" pipe and replaced with a 4' telspar pipe with cast iron cap.