Certificate of Location of Government Corner

ID#: 853005 **Description:** W SEC COR 30 31 85 **Date Set:** 8/7/89 **County:** Olmsted

Section: 30 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls 0.3' east of centerline of CSAH 5 and 14' south of centerline of twp road east
1" square pipe with cap 200.0' east and on line to 852905
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 31 & 36. 80.0 chs. Set corner post to sections 25-30-31-36. RPs- 10 " burr oak N4°E 243 links, 10" black oak N1°W 719 links.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old road Bk.--Road No.66 surveyed the road on the west line of sections 30-31.

11-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Bk. Road No.82) surveyed the road between sections 30-31.

1912 Charles Larson, Dodge County Surveyor found limestone here and set a 2"x6"x6" limestone and stake at the 1/16 North(Bk.A Pg.23 Dodge County Records).

1940 Dodge County Hwy Dept. (Dodge county highway department Bk.22 and Bk.131) assumed corner at center of road east.

5-9-1980 County Surveyor dug at double the line and measure from the w 1/4 corner 30 (found) over the 1/16 south (found Larson's stone). Found 4"x5"x10" limestone standing beneath the old road 3 1/2' deep. Found the stake mark on the north side of the stone. Drove a 1/2"x22" iron in the stake mark and bent over the stone and put the top of a CIM on the south side of the stone. Set a 5/8"x3' rod at the road surface and over the stone. RPs- Punch hole top west end concrete culvert SW 44.27', punch hole top east end concrete culvert SE 42.25'.

7-15-1985 County Surveyor, this corner may be destroyed by road construction. Found 1" square pipe with cap set 200.0' east and on line to NE 31 in 1978.

8-7-1989 county highway department set 5/8" brass plug in centerline CR #5. RP-county highway department disc in pp WSW 56.82'.

6-1-2004 County Surveyor found 5/8" brass plug at surface in good condition.

10-23-2006 County Surveyor found 5/8" brass plug at surface in good condition.