Certificate of Location of Government Corner

ID#: 853006 **Description:** W 1/4 SEC COR 30 85 **Date Set:** 8/7/1989 **County:** Olmsted

Section: 30 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls 0.4' east of centerline of CSAH 5 and in centerline of Dodge CR 22 west
Spike & Disc in Oak NE 126.61'
Spike & Disc in small tree E 58.72'
Top NE corner of step of house SW 110.33'
Most ely NE corner house foundation (concrete block) SW 104.88'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; North between sections 25 & 30. 40.0 chs. Set quarter section post. RPs-18" black oak S89°E 38 links, 6" black oak S40°W 73 links.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book--Road No. 66) surveyed a road on the west line of section 30.

11-1874 Thomas Hunter, County Surveyor, (Bk.A Pg.264 No.262 and Old Field Book 4 Pg 6-7) 1/4 post missing. Found stump of SE bearing tree with marks all plain, the SW bearing tree grubbed out, but found piece of old stake in the ground. Set boulder stone in its place 16"x9"x7". He used this corner to set the center 19.

2 7 3-1892 Thomas Fraser, County Surveyor, (Bk.A Pg.471 No.452 and Old Field Book 8 Pg.11) found stone after finding remains of east witness tree stump, stone was set by Thomas Hunter. Took new bearing tree; 8" black oak 8" east 45 links.

1-1896 William Fraser, County Surveyor, (Book A Pg.589 No.535) found corner as located in Survey No. 262 and also as given in Survey No.452 with bearing tree as taken in that survey: 8" black oak east 45 links.

9-1910 Charles Larson, Dodge Co. Surveyor (Bk.B Pg.124) found hardhead boulder.

9-1912 Charles Larson (Bk. A Pg.23 Dodge County Records) found boulder.

1940 Dodge County HWY Dept. (Dodge county highway department Bk.22 & Bk.131) shows hub at junction with road west.

11-1978 Ron Murphy, Dodge County Surveyor, found boulder 1'x0.8'x1.0'.

5-7-1980 County Surveyor dug over iron set by Murphy. Found iron to be a 120d spike with twists. Found spike to be over an 8"x10"x15" boulder approx. 2' deep. Set the boulder back and set the spike back at the road surface. RPs- CSD NW side pp#23204 NE 103.09', CSD SW side 22" pine on south side driveway east SE 130.98.

7-15-1985 County Surveyor, corner may be destroyed by construction. Found 1/2" rod set in center of road 164.80' westerly in 1980 slightly bent. Replaced with 5/8" rod in same hole. Additional RP to corner- Most ely NE corner of house foundation just below siding, SW 104.78'.

8-7-1989 county highway department set 5/8" brass plug in centerline of CR #5. RPs-Top NE corner of step of house SW 110.33', spike & disc in small tree east 58.72', spike & disc in oak NE 126.61'

6-1-2004 County Surveyor found 5/8" brass plug at surface in good condition.

10-23-2006 County Surveyor found 5/8" brass plug at surface in good condition.