Certificate of Location of Government Corner

ID#: 853504 **Description:** S 1/4 SEC COR 35 85 **Date Set:** 6/7/99 **County:** Olmsted

Section: 35 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 14 and 1' east of centerline of twp road north
Ref. pipe NNE 75.47'
Punch hole in top E end CMP NE 34.17'
Punch hole in top W end CMP NW 36.03'
County highway disk in PP #23552 NE 51.25'
County highway disk in PP #23540 S 35.13'
County Survey Disk in N side TP with box along side WNW 111.89'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 2 & 35. 40.0 chs set quarter section post. RPs-12" black oak n34 1/2°W 232 links, 4" black oak N79 1/2°E 141 links.

1-1862 S. McDowell Pg. 67 No. 94 shows 1/4 corner used to breakdown west 1/4 of sec. 35.

2-1882 Thomas Hunter (Pg.373 No.364), County Surveyor used the line of the old fence running south for the E-W location of the corner.

1935 county highway department (Bk.78 Pg.74) found a horsehoe with small pieces of glass around it.

9-1948 John Kerr (Bk.39 Pg.61), County Surveyor dug up 1/4 section corners 2-35 and referenced.

1966 county highway department (Bk.318) found 60d spike riser over a pipe.

9-7-1976 County Surveyor dug with the backhoe and found a nail over a pipe. Found the recorded horsehoe 3' deep on old road 1' north and .4' east of the nail. Dug to clay 4 1/2' deep, but found nothing further.

9-8-1976 County Surveyor set a CIM over a 1/2"x2' rod as the corner at the location of the horseshoe. Removed the pipe. The corner is in the center of the E-W road and in line with the fence south.

5-15-1998 County Surveyor found CIM in good condition. Referenced corner before cold recycling bituminous surface of C.R. #14.

9-25-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-15-1998 reference.

6-7-1999 County Surveyor set 1" square pipe with cap at surface.

3-26-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.