Certificate of Location of Government Corner

ID#: 953204 **Description:** S 1/4 SEC COR 32 95 **Date Set:** 1/11/2001 **County:** Goodhue

Section: 32 **Township:** 109N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of E-W twp road and 39 1/2' east of centerline of driveway north
County Survey Disk in E side PP NW 42.37'
Punch hole in W end CMP ESE 110.18'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West corrected on the south side of section 32. 40.0 chs. Set quarter section post. RPs- 7" jack oak N70°W 83 links, 6" jack oak N55°W 64 links

5-1889 Thomas Fraser (Pg.428 No.416) County Surveyor used this corner. He found a stake at North section corner 4-5.

8-1939 John Kerr (Bk.1 Pg.1) states that the corner comes in or under a stone arch bridge. Found nothing. Set a 60d nail at double the line and measure from the SW corner section 32 over the 1/16 east. RPs- NE 21.93 to south edge L iron post guard rail, N 17.06 to the south edge L iron post guard rail.

9-1976 Olmsted County Surveyor found large iron near the west end of a small stone arch bridge. Accepted this iron as the corner. T. Ferguson set his iron over another iron found in bridge which was possibly John Kerr's.

7-1981 Doug Rude, Crew Chief for Yaggy Associates, Inc., found a 1 1/2" frost pin 0.1' below gravel surface of bridge. The iron is at the southwest end of bridge. New land ties were measured. The iron is accepted as marking the Public Land Survey corner.

9-11-1985 Olmsted County Surveyor found large iron with smashed top. RPs checked- SW corner house ok, SE corner house changed. New RP is CSD in east side pp in driveway NW 42.33

9-18-1991 Olmsted County Surveyor tied out large iron for road construction

1-8-2001 Olmsted County Surveyor found square iron down 1.2' in good condition. Small stone arch bridge now gone. Checked ties.

1-11-2001 Olmsted County Surveyor removed square iron and set 1" square pipe w/cap at surface from 1991 tie out.