X 12-2-76 Accepted pipe on corner #522206 (1)

Orion 105-12

section corner 21-22-27-28 Dabzark.

5-1893 W Fraser. P506 no 476 L22 Fox, Hasty

found stake placed by Hunter. & 3 B T stumps, tested OK

drove new stake.

1/16 North set stake M & L 19.95

also stakes both North & south above 1/16 cor M & L 9.97 1/2

1/16 east set stake M & L 19.92 1/2

also stake between above 1/16 and sec cor M & L 9.96 3/4.

also stake 9.93 3/4 east of 1/16 cor north of sec cor.

4-1898 W Fraser P621 no 564 L28 L Oliver.

found corner set P 506.

Meas south 39.79 to 1/4 stone. (owner)

1948
~~1947~~ J Kerr B 40 P 27 } Checked tie and found post missing S.W

1939 ~~1940~~ Co Hwy Dept B 105 . P 12.

Corner post maintained as corner

+ in rock NE 22.67 above spring

B Tree E 15.0 blaze near bottom red oak

center road west 164.4 in fence line

12-2-76 Accepted John Rice pipe as corner and reset. Corner 3' NE of C.P.

R.P.'s Cross chiseled in rock ledge NE 22.62

Spike and CSD SE side 15" blazed

Br. Oak SE 16.75

Spike & CSD N. side 15" Burr Oak NW 13.08

SECTION CORNER 21-22-27-28 ORION 10S-12 (2)

North between SECTIONS 27+28 - VAR 11°35'E - SFE 1/4 COR. 27-28

GOV. NOTES - OCT. 6, 1853

80.00 chs Set post CORNER to SECT 21-22-27-28

#522205

BR. OAK 18 N 78 E 40

BR. " 11 S 31 E 49

RED " 10 N 59 W 33

BR. " 15 9 85 W 378

July, 1856 Thos. Hunter Pg. 12 No. 19 shows Sec. Cor.

1/16 West 19.78 chs. then 9.89 chs. to 1/64 Cor then 9.89 chs. to 1/4 Post.

B.T.'s to 1/16 west (N 15 1/4° W 21) & (S 87 3/4° W 30 lks.)