#522404

/ 6-20-73 set C/M orig. 5/8" x 2' rod. from orig gov't bearing tree and east-west meas.
cont 3-6-75

1/4 Corner 24-25 Orion 105-12.
4-1878 Hunter P336 No 330 L 24-25 J Greenlee. T Moore etal.
Corner gone, in cultivated area. One witness tree still standing but did not agree anywhere near midway as set by govt surveyors. As no other trees set stake midway and where meas from tree intersected line - 25 lks (82.5' gov't bearing S 36½ W - no final bearing after resetting corner given
-16 east and west set stakes M & L 19.91 3/4 1314.55
bearings E- N 89°55 E W S 89°15 W shows kink.
16 center NE 1/4 25 set stake M & L on N-S 1/16 line M & L.
20.03 3/4 1322.48

6-13-73 ran electronic traverse to within 100' of corner post of fences running N and W., found orig govt. bearing tree 5" brOak S 36½ W 125 lks 82.5'. tree now well over 3' dia in perfect shape and condition. about 81' from center tree to corner post. (nail SE side) after completing traverse set C/M over iron at 82.5' from Center tree and midway on north line section 25. Corner comes about 1.65 NNE of center new corner post. nail in SE side huge oak 82.32

Meas from corner = see field books on electronic traverse data.

GOV. NOTES - OCT 6, TREE
WEST ON TRUE LINE BETWEEN SECTIONS 24 + 25
VAR 10° 10' E
40.00 SET BR. SECTION POST
BR. OAK 5 S 36½ W 125
80.00 TO SECTION CORNER

BT STILL HERE ON JUNE 13, 1973 RB