/ 8-10-78 CIM

#523606

¼ corner 35-36 Orion 105-12.

5-1886 Hunter P405 no 394. ∠36. Lwyle, Morrison
Corner and witness corner gone. found stump of ∠EBT.
reset witness corner 50 lks north of true corner which
comes in pond edge.

2-1902 W Fraser P30B. ∠35. Milligan, Bernard
Hander, Olson.
drone iron stake as corner. 73 lks from ∠EBT stump
marks still plain. and 50 lks from witness stake set by Hunter
New B tree 8" Burr oak. N 56° E 10½ lks.

1/16 west drone sleigh shoe. M&L 19.97½ N 89½° E
drone stakes for fence line to center 35.

8-10-78 Corner comes in deep fill of T.H.30. Did not dig.
Set a CIM over a ½" x 2' rod at double tte

GOV. NOTES - OCT. 6, 1853

North between sections 35 and 36

VAR 10° 55' E

6.50 Enter dry bottom [redacted] E+N d 120

13.50 STREAM 80 LKS AND RUNS East

30.05 Enter pond E+N LEVEL

40.00 IN pond

40.50 ~~40.05~~ SET WITNESS CORNER TO QR. SECTION CORNER

BR. OAK 8 S 68 E 73

BR. OAK 6 N 65 W 78

44.00 LEAVE bottom AND ENTER LEVEL

Aspen thicket E+N

60.00 LEAVE thicket, ENTER timber A 130

---

line and measure of the 1/16th West. The corner came in line, with fence So. and 21.3 So of ℄ T.H. 30 and 25' East of ℄ of driveway Nord.

RP: CSO in C.P. on West side of driveway N NNW 99.95

V523606

(41)

6-10-99
MW, RF, AE

1/4 Cor 35-36 105-12 ORION

Fd CIM in good condition
Just off South Shoulder
T.H. #30 The Corner Fells
21.2 South of ℄ CR #35 &
27' East of ℄ driveway
north @ mail box # 13011

V523606

(41)

6-10-99
MW, RF, AE

1/4 Cor 35-36 105-12 ORION

Fd CIM in good condition
Just off South Shoulder
T.H. #30 The Corner Fells
21.2 South of ℄ CR #35 &
27' East of ℄ driveway
north @ mail box # 13011