X 4-28-77 Set CIM #531205 rattlesnake crossing (1)

section corner 11-12-13-14 Pleas. Grove 105-13

2-1874 Hunter P239 no 241 d 13 J. Fait, E Derby found orig corner standing. d W B T standing as well as all other stumps. found stake to be 20 lks two for west. Broke it off and set it as good as one could in frozen ground then all B True checked good. 1313.4

1/16 east set stake M & L 19.90 a temp stake 137.58

then set temp stake 6163 east of above 1/16 corner.

9-1893 W Fraser P532 no 495 d 11 C Russell.

could not find stake driven when surveying d 10 1-1893 set new stake by B True - Mr Campbell will set stone.

5-1900 Robt Fraser P675 no 600 d 12-13 Town board.

found stone set after survey P532

5-1949 McGhie ~~set~~ 3/4" pipe X15" long. by A. Armstrong 1938

SE cor barn foundation.

12" walnut

corner fence post

Spike 16" stamp

Meas north 5101.7-? ee.

South 5272.3.

W.N.W.	192.5
N.N.W.	179.3
S.S.E	95.4
S.W.	50.8

1938 data

See Card #2

4-25-75 Found 3/4" pipe useing only remaining McGhie tie to SE corner barn Foundation. Left as Found.

R.P.'s: Punch mark in top clamp of south end of 18" driveway culvert. N. 145.85'

C.S. Disc in N. side power pole # 40498 NE 165.23'

#531205

B97 P13 A. Armstrong notes
C H D. Extra Card. Cor 11-12-13-14 Pl Grove

found ¼ 11-14. shown by Frank Campbell. 1938 B97 P15
Quote Frank Campbell and Roy Nesbit showed me where they thought
this corner had been located. They said there had been a stone
here years ago but they were certain of its location within 8 or 10 feet.
– The Mid point between F & E (FNW 12) E-SW 13 did not agree
with their location by 85.3 the mid point 5187.0 being 85.3
south of the point where they showed me and where I finally
relocated the corner S 5272.3 N 5101.7. There is an old
fence west of the river running all the way from point A ¼ 11-14
which fence Frank Campbell says has been in place since stone
was in at "B" (11-12-13-14) and which he believes is on section
line. I produced this fence line east to "B" and the line fell
very close to where Campbell & Nesbit said corner should be.
– Considering the testimony of Campbell & Nesbit and its agreement
with the fence line running from the west, I decided that

(over)

it was more dependable and would more likely locate the corner in its original location than would the method of setting it midway between F & E first because the latter location did not agree or line up with any thing else and secondly because the extreme roughness of the land between F & E makes good chainage improbable, and it is most likely that the original chainage was very poor. So I set section corner on line with fence from west at a distance of 2637.4 from "A" 1/4 11-14 - dug considerable around this spot but found nothing. 2637.4 is meas given by Wm Fraser P532 No 495 9-1893. 2637.4 is N.E. meas from 1/4 Cor 11-14 West not East.
- could find nothing at 1/4 12 or 1/4 E cor 12.

Drove 3/4" pipe 15" Long at Sec. corner

Ties: S.E. Cor. of Elm 48in W.N.W. 192.5
12" Walnut - N.N.W 179.3
Nail in 16" Twin Hemp - S.W. - 50.8 last stump on E. end of

#531205 #3

Section Corner 11-12-13-14 Pleasant Grove 105-13

5-76 Corner will be set on line from ¼ Cor 11-14 over the corner post at 1/16 E and midway between ¼ Corner 11-14 and ¼ Cor 12-13 (Location of ¼ Cor 12-13 not final but will not vary significantly E-W)

4-28-77 Set a CIM (down 12") over a ½" x 2' rod as the corner 4.41 N and 9.12 W of the 15" pipe (removed). Corner set as described above.

RP's: Punch mark in top clamp S. end 18" CMP in driveway N 142.95

CSD N side pp #40498 NE 165.23

SE corner of concrete block pump house NW 194.6

Cor' Notes on Back

Govt Notes M.G. Kerrick 1851

80.00 Stl post for Cor. to Sec 11+12-13+14

Elm 13 S 53 W 21
" 8 N 118 W 36
" 15 N 116 E 52
" 8 S 56 E 22

5 – 1885 Hunter (unrecorded survey in Old Fieldbook #14, Page 38) shows 1/16 W midway (20. chs)