#532104 (1)

8-13-1964 set CIM over ½" galv pipe under E-W fence.
8-25-77 drove pipe dup & set a witness CIM over
C-1979 New CIM
¼ corner 21-28 Pleas. Grove 105-13.
No records - ½" pipe set by J Kerr in earlier survey
Kerr BK 26 P. 37-38 & 55
on section line N & L.

8-1964 J Kerr to place & preserve corner.
found pipe under fence after meas line from west.
set CIM under fence with pipe driven below.
No fences N & L at corner. However a fence running
north some 10 rods or more runs north on a line
about 2' west of corner as you sight north on fence line.
Nothing To tie to.

8-25-77 E-W fence now gone and area cultivated. Found CIM plowed out and broken but pipe still in place. Drive pipe deep and set the bottom half of the broken CIM over the pipe and set the top half along side. Corner approx 6' So of line of new fence East which begins approx 63' East of the corner

For Transit Tie taken see Pleasant Grove Field Book

RP: CSD in S. side wood fence post (most westerly of 3) in new fence Edit ENE 63.2

Cedl Wolfe M.C. Karrick 1851 East Random
10.00 Std temp Std post 21+78
WTS1 on line between Std 21+78 & 10°6'
10.00 Std 111 Std post
Black Oak 8 N 35 E 35+
Blk Oak 3 S 10 W 10+

#532104 (2)

¼ Cor 21-28 Pleasant Grove 105-13

6-13-1979 The ½" rod used for a transit tie in 1977 is in a frost boil in the road this year and we found it tipped over, so we walked into the corner and set a new CIM in place of the broken one and took references. The C.I.M is 1' deep in cultivated field 6' South of a new E-W fences. Set a survey marker sign 5.55 North in the E-W fence line.

CSD in South side of wood fence post ENE 63.24