1 7-23-74 Set B.I.M. over a 3/4" x 8" rod M&L 2651.78

#542304 (1)

1/4 corner 23-26 Hi Forest 105-14.

6-1899 Pt Fraser P659 No 587 &26 Town Board.

Corner lost - set stake M&L 40.15½ (2650.23'

West to corner reset at NW 26.

East to corner reset at NE 26.

- set stone 50 lks west of stake set as N 1/4 26.

No county notes on 10-1924 run. N & S.

corner coned be reset. - orig stone S 1/4 26 over

center 26 orig stone and establish northing & southing.

7-23-74 Set a B.I.M. over a 3/4" x 8" rod M-L 2651.78

(over)

Punch hole North end 18" c. nip (driveway)
C. Surv disc South side fake pole
C. Surv disc South side PP # 38876
North end of Conc. of bridge over Red river

Gone or moved in construction

N.E		41.77
N.W.		65.06
E.		27.66
South		116.1

1/16 West
Drove 12" North side of stone ——— Stake is 0.4 W. of midway &
0.2' N of Sec Line
E-W
65 South Dr
when the E-W's do this corr. will move because they plat
on putting a new E-W Dr in along this line.

C. Armstrong 1906 Book B p. 108-109
Plat indicates Stone as N. 1/4 26 with 1/16 Stake West
Gov't Notes Jan 6, 1853
40.00 Set temp 1/4 Post
West on true line between Sects 25-26
40.10 Set a 1/4 Post with V 7° 10' E
Vaguard 0.4 Conf 6" Post Depressed
Charcoal, made Chamb 4 Ft 12 Planted
Orange Orange Scarf Pines 0.4 to North

1/4 Corner 23-26 High Front #542304 105-14 (2)

3-24-81 (1981 Reman BK.) Took R.P.'s to corner before road graded (CIM with top broken off). Set a 1" sq pipe with cap 116.62 West and on line to a P.K. in large fence post 94.70 West of the 1" sq. pipe (also spiked in top). Put a survey marker sign and post .5' North of the 1" sq. pipe

4-23-96: FOUND P.K. @ SURFACE OF CRUSHED ROCK ROAD SET FROM (1981) RP PIPE WEST. DUG DOWN TO SMASHED TOP CAPPED PIPE. CHECKED TIES AND FIXED UP PIPE. PUT PLASTIC CAP #15809 IN PIPE 9" DEEP. THE CORNER FALLS IN ℄ CR #120
CSD IN PP# 38876 EAST 50.07'
NORTH END CONCRETE BRIDGE SOUTH 69.2'

116 SO 58

"542304" D 2-17-98

1/4 23-26 HIGH FOREST 105-14

FD 1" PIPE DOWN 0.8' IN GOOD CONDITION.