#553465

section corner south 33-34 Rock Dell 10 S-15 E.

6-1877 Hunter P 319 no 313 & 3 10 4-15 J Brewer. J Saulsberry. J Rickert

In survey Sec 33 did not find any sign of corner land brush & liner made line a "muddle" as refered to this survey for setting of corner. P283.

- corner of course gone. -
- meas line from & E cor 34 to & W 33 making 80.26 for each mile established corner at that meas but not on direct line as gonl notes show it was not straight
- meas north to 1/4 33-34 40.25 as established which is limit for gonl error in chainage.
- using this section corner as pivot established lines straight east to & E 34 to set corners east

over)

and straight line west to N W cor sec 3 T 4-15
a stone found in post hole covered by Mr Gordy as true cor.
- set stake marked as corner. which corner.
4.89 chs east of N 1/4 S 3 established M & L 40.02
on S 3. (322.74 W)

9-1853

61.40 Creek 50 lks wide runs NE
80.00 set post for corner to Sect. 33 & 34
Burr Oak 10 N 8° E 41 9/10 lks
Burr Oak 20 N 18° W 59 6/10 lks