X should get CIM in here

#600605 (1)

section Corner East 1-12 Doner 106-11 E of Winona Co.
7-1890 Thos Fraser P444 No 429 S12 E Co Line
for C Carter and others.

See also Fd Book 6 p. 16-17
J.F. 1890

Corner placed over 20 years before by a Mr King in center of mound by old stake when road first graded up. Corner never found but often looked for. On digging a half day started to run in corner. On digging further east [illegible] while others seeking corners east Mr Carter found stake and small 10" triangular stone that Mr Carter & Mr Pringle had seen placed 20 odd years before. We had tracks compacted and proved it correct Placed 4 x 10 x 25, pointed with old stone below and stake by side. "Exact Point, (this was about 8' east of fence) witness." Likely fence south.

Gov't Notes: 1853

N. 80.00 chains: Set Post in mound for Corner
Made mound & Trench & deposited
Charred Stake & Hawthorn Seeds

Oct. 10 & 11, 1974 Co. Surv. Our corner 6.3 So & .3 E of Burn's 2" pipe (See Dover Field Book)

dug very large hole (± 20' Square) with Tractor looking for T. Fraser's 4"x10"x25" Stone over Small Stone. Could not find large stone but found Small Limestone lying flat down into clay with dark hole in clay which Could have been old Stake hole, used This flat Stone as being Correct location. Also found 2" iron pipe (4' deep) in E. Road which Could have been E.C. Burn's Corner - Winona & Surveyors. Removed iron pipe which was about 6.3 feet - directly North.

June, 1857 John Fraser Pg. 45 No. 67 Did Breakdown in 1 & 12
Sec Survey

East Sec Corner 1-12 Dover 106-11 (2)
#w00605

3-18-1983 - County Surveyor - Could not find
1/2" rod set in 1974, also dug 12' South to
double over 1/16 Cor (fence east) South of this Sec Cor
did not find anything. Dug 3' down and 4' east cut
to clay

Be Careful! 1/2" rod set 3-18-53 as traverse pt may ST. 11
be in place approx 1.8 South of Car jack tube - set
1983 Remen Buck to RPS to 1/2" rod

3-20-1983 - RWB Survey in Sec 7-106-11
Set 18" piece of Car jack tube as corner from
Traverse from West and checked from a Traverse
From S.E. Set @ 1974 1/2" rod location

Ties: Spk in Cor fe post - South - 28.90
Spk in Brace post - S.W - 29.80
So. edge of Sign Post - S.S.E - 8.5

3-1980 Roger Brand set the 1/16 South, a 3/4" iron pipe with elbow on top. Falls 7' North of fence East and 1.0' West of N-S fence. E-W fence probably will be taken out soon (1321.67-1321.67)