10-20-83 Set CIM

#610405 (1)

Section Corner 4-5-8-9 Doner 106-11

Field book 15 pg 89-94

6-1900 Robt Fraser P686 No 610, S 8, H Huff & others found corner post with stones packed arround it claimed by H Betry as True corner. 1316.53

- 1/10 west. set boulder stone & stake 19.94 3/4 M & L.

- 40.19 1/2 south to 1/4 cor set (stake, small stone by side)

2651.55

GOV. NOTES - 1853 - J BALL

SET SECTION CORNER POST M & L 40 chs, 2640.

9-28-83, Sec. Cr. 4-5-8-9: Dug with backhoe in the center of the E-W road and in line with the fence South

First found a cedar post stub down 3' and running 1' into clay. There were several pieces of limestone and a flat boulder just above the post stub but scattered about a little by road construction. This post stub .46 West and .9 South of the t.n. here. There was a second post mark (no wood) .16 W and .1 North of the t.n. Dug from the red cedar post stub for 2½' West, 4' East, and 3' North, and 1' South but found nothing further. There were a few pieces of glass with the cedar post also.

9-28-83, 1/16 West: Dug from the t.n.o as follows:



Found cedar post stub 2.45 N and 3.96 E of the t.n. (much like cedar post #1 @ 4-5-8-9)
Found another post mark (no wood) 1.08 N

#610405 (2)

Section Corner 4-5-8-9, Dover, 106-11

9-28-83, 1/4 Post (cont) and 2.08 East of the t.n. Fits R.F. measured best

Also found small circular black mark (poss. stone loc). 6 North and 3.4 East of the t.n. Clay down 3'. Very little black dirt. Post mark found in clay

See comments BK for actual RFs

10-20-83, See Cor. 4-5-8-9: Set a CIM over a 1/2" re-bar at the location of post mark found 9-29-83 (post mark, not cedar post) Corner in ℄ E-W road and in line with the fence South. Nothing to the to except "Bunbaker" See Drwg 10-106-11-1

7.