10-20-87 CTM

#611006 (1)

1/4 corner 9-10 Dover 106-11.

1945 Co Hwy Dept B 168. PS.

drove nail for assumed corner.

spike & disc	in 18" maple	NW	73.6.
" "	power pole	NE	95.5
" "	" "	SW	73.4

GOV. NOTES - 1853 - J. BALL

SET 1/4 SECTION CORNER POST m+L 40 chs 2640'

CORNER COMES IN CROSS ROADS COMMON LAND E+W OF ROAD

CORNER IN LOW BOTTOM LEVEL AREA ELEV. 1105

10-12&13-83 Dug small hole over PK found shot here. Found a RR spike between layers of blacktop RR Spike .14 South & .44 West of t.n. Found a 1" x 32" pipe beneath blacktop (blacktop 1' thick here). Pipe .36 South & 1.54 West of the t.n. Found nothing further. Road in cut here. Fill to clay 2' deep.

10-20-83 Set a CIM over a 3/4" re-rod @ PK location as corner. Corner 1' East of ℄ C.R. 10 and in ℄ rd. East and 4½' North ℄ road West.

RP's C.S. Disc in NE side power pole NW 58.65
CS Disc in SE side power pole SW 85.72
Spike in NE side corner post SE 58.16
Spike in SE side corner post NE 55.20

1/4 Corner 9-10 Dover 106-11 #611006 (2)

9-1980 1/4 Cor 9-10 : Ron Olson set PK nail over iron detected (dupped)