#611505 (1)

X

Section corner 15-16-21-22 Dover 106-11.
5-1891 Thos Fraser P449 No 432 L21 Bracket, Idaho.

corner came in bridge abutment area -
9 lks SW & SE corner bridge.
-1/16 west set stake 20.08 N & L 1322' ±

Co Hwy Dept
Cross chiseled in bridge.
+ right bridge curb 10.6
+ left " " 10.6
+ South end bridge 37.5

over)

Hunters RR tie
5.40 chs south to ℄ rails
15.36 chs west to ℄ rails.

9-10-15-16
1980
Ron Olson Fd PK
.32N & 1.54E of
Sec. Cor.

7-22-75 1/16 W Found 2" x 14" (bore) x 14" limestone coming to point 1' deep and 1' east of new 5" corner post. Bent 1¼" flat iron around stone and set 1¼" x 24" flat iron on east side with top over stone.

GOV. NOTES - 1853 - J BALL
SET SECTION CORNER POST 80 CHS NORTH OF 21-22-27-28

PK nail inplace in 1975 is 0.32 North 1.54 East of Sec. Cor. established from west - (Control Pt K-5 is ±187' SE)

SEC COR 15-16-21-22 DOVER 1806-11 #611505 (2)

4/8/86 POINT FALLS UNDER BRIDGE 17' ± N OF FACE OF S CONCRETE BRIDGE ABUTMENT, AREA APPEARS TO HAVE BEEN DUG OUT OF SOUTH CREEK BANK & PROBABLY CUT SEVERAL FEET. DIPPED & DUG 3' DIAM. HOLE 2' DEEP (ALL MUD) FD NOTHING. BELIEVE NO CHANCE FOR COR

