#611904

¼ Corner 19-30 Dover Twp 106-11

9-1892 Thos. Fraser P.497 N.469
Corner gone, in re setting Sec. Cor. 19-20-29-30 apparently dug for this ¼ Corner but evidently found Nothing. Used Total Msmt from SE Co To S.W. 19 To set Corner at 19-20-29-30

July 1975 Co. Surveyor - dug hole with backhoe found that road had been washed out To bedrock which is why T. Fraser probably did not find Corner. Set CIM over RR Spike on prorated Msmt, ¼ Line after Setting 19-20-29-30. Corner lies 1-2' So. of ℄ E-W Rd
R.P.'s - Co. Surv. Disc in RP. - N.W. — 41.2
Co. Surv. Disc. in Cor. Se post - E.N.E. 126.15

GOV. NOTES - 1853 - J. BALL

SET 1/4 SECTION CORNER POST MTL 40 chs WEST OF

19-20-29-30

ENTIRE MILE 79.70 52.60 2 WEST 1/2 2620.2

STREAM 10 LKS WIDE WEST 3 chs -198