8-1-1961 C/M set by County Hwy Dept. #612706 (1)

1/4 corner 27-28 Dover 106-11

4-1871 Perry P182 No 193 S27 N Pike

found remains of old stake, set new one.

-1/16 north set stake M&L 19.93. = 1315.38

8-1961. Co Hwy Dept B240 P. 5

set C/M in place 1/2" rod & former corner.

origin of findings unknown Δ 0°1'30" lt going ~~south~~ north RB

Dec 18" pine W.N.W. 67.8

Hub in fence line east 70.05 over)

Dirc tele pole. NE 93.84

" " SE 71.1

Meas south 2633.2 to 27-28-33-34

Meas north 2627.3 to 21-22-27-28.

9-1935 C.H.D. Book# 83 page 74 set this 1/4 Corner after Finding the east 1/4 Corner of sec 27 & Center of 27. Then doubled line & distance to set 1/4 Cor 27-28 (2637.0 m&L)

(Wrong way to set 1/4 Corner)

1/4 CORNER 27-28 DOVER 106-11 *61x706 (7)

GOV NOTES - 1853 - J BALL

SET 1/4 SECTION CORNER POST M+L 40 CH: 2640

11-2-1979 Set 10" CIM over a 5/8" x 30" iron Rod 3.21 North of the T.M. and on line T.M. to Sec Cor 21-22-27-28. We found McThie P.K. in C.R. 10 West of the NW Cor McGougall Subdivision and used that measure of 868.0 to set the corner N-S (See McThie 8-21-1969 Survey)

References made

1) PK nail & Washer West 2 and South 2 square from NE Cor cement Wet backedge under I-90 Bridge SW 133.46

2) PK nail in crack East 2 and South 2 square from NW Cor cement East backedge under I-90 Bridge SE 133.89

3) CSD in pp WSW 5 8.6

5-26-82 Rod-Ed

Set 2 ... for additional references

3/8 ... 24 ... 1/2 3R*10 N.W. 51 02 (1" ... of CR*10 ... pm)

5/8 ... to East 1/2 CR*10 N 2 51 55