Card #1
#613304

1 6-18-76 Dug Sd Nothing
7-5-76 Set ½" rod M&L
1-4-83 Set 1" square with cap. 0.25 South Conc. ℄

¼ Corner south ½ 33 Dover 106 - 11.

North ¼ 4 Elmira 105 - 11.

10 - 1897 Jr Fraser P 612 No 556 S4 Jr Colsan

Corner gone, set temp point M & L 39.94½ (~~2637.37~~ 2636.37

Gov't notes: 1853 Set Post for Qr. Sec Corner & drove charred stake, built mound with trench.

6-18-76 Dug on line and at W.F. measure from N 4-5 to N 3-4 (shaft). Dug 3 [6] 5. Bedrock at 4' depth. No black dirt. Found nothing. Point came 6' E of fence S.

7-5-76 Drove a ½" rod on line and midway between section corners.

R.P.'s Electric fence post drive down ($\frac{1}{2}$' E of fence) S. 86.92'

CSD in PP. NW 82.31

8-8-76 Tied corner for road grading

Set ½" x 2' rod & hub 2' East of fence So., So. 114.26 and tied $A_z = 93° 34' 22''$ from cupola in center of barn roof East to the ¼ Corn.

5-19-82, S¼ [redacted] Cor. [redacted] 33: ½" rod set 7-5-1976 now-gone or buried in newly graded CSAH 10. The fence line South is buried to the tops of the steel fence post with dirt from drainage ditch dug on West side of fence so ½" iron set by fence South in 1976 are buried and power pole with CSD NW 82.31

Card #2

#613304

S. 1/4 Cor. 33, Dover 106-11
N. 1/4 Cor. 4, Elmira 105-11

5-19-82 continued: taken 7-5-76 is gone. Reset 1" sq. x 17" pipe as corner midway and on line between the 1" sq. pipe set at S. 32-33 today and the CIM at S. 33-34

RP's:

Punch hole in top E end CMP for field drive NW 51.63

CSD in 2nd brace port SSW 61.81

CSD in power pole NE 102.97

1-4-83, S 1/4 Cr 33: Set corner, a 1" sq pipe/cap .25 South & crack in conc. of CR 10. Set corner ~~[illegible]~~ M&L (2636.58) after running line and meas.