X 6-22-76 fd Stone - set a ½" rod at road surface #1

1-4-83 set 1" Spruce with cap 1.90 South cor. 2 #613305

section corner south 32-33 Dover 106-11.
North 4-5 Elmira 105-11.

10-1897 H Fraser P642 No 556 S4 H Colsan.
found remains old stake in center road where
S M Carpenter said old stake stood to his memory.
48 lks from end of tree row on south side road
running west.

Drove new stake with 2 stones by its side in
place of old stake.
- 39.94 ½ east to temp stake Not marked
- 39.97 south to temp corner set ⅓ distance to ¼ 8-9.

(Need to Will on this meas S. over)

Check This. Sec 5 should be shown

1936 Co Hwy Dept Book 83

found rotted stake with 2 x 8 - 18 limestone

tel pole N.W. 45.6 — Cor. fence post L 28.9.

fence post S.E 48.3

1935 Co H D B 95 P 7 found old wood stake 18" deep with 2x8x18 limestone on north side of stake - used stone

1935 Co H D B F 3 P 2 found old wood stake with limestone 2x8x18 on N side of stake set stake for Top of stone

Lp on tel pole N W 45.6 Lp on F P S 28.7

Lp on F P S E 48.3 263 1.4 W west to S 4 32

-B83P21 Tie — Hub in E W fence line L E 26.0

Hub in fence South 49.0 Lp on tel pole N W 45.6

263 8.0 west to S 4 32

Gov't Notes: 1853 - Set Post & dug Trench

B.T.'s Black oak 10" N 22° E 135 links — Burr oak 7" S 41° W 183 links

#613305 #2

Section Corner South 32-33 Dover 106-11
North 4-5 Elmira 105-11

~~6-~~-76

6-17-16 Dug in C.R. # 10 + found a C.H. dept hub over 2 Limestones over + stake running down 12" ±. the stones are 3½" deep. left + ½" x 20" rod at stake hole + set a ½" rod at road surface.

R.P.s

Co. Surv. disc in R.P.# 1981
Co. Surv. disc in tele pole
Punch hole in S end C.M.P.
Corner falls 1' East of fences South + in ℄ of road North

1982

N E	47.95 gons
N W	57.90 gons
S W	43.54 gons

8-8-77 Tied corner for road grading. Set a ½"x2' rod + hub 1' E of fence So So 85.07 and on line to ½" x 2' rod set .5' E of fence So. & So 173.64

5-19-82, S. 32-33: This corner is now in deep fill of newly graded road, CSAH 10. All R.P.'s taken in 1976 are now gone. Found the two ½" rods set by the fence line South 8-8-77 and used them to reset the corner, a 1" sq by 13" long pipe for the C.H.O. to use for staking new concrete pavement. Will set corner in new pavement by same method. Pipe came .18 N. and .15 E. of spike Fd at road surface

1-4-83 South 32-33: Found that Southerly RP rod set 8-8-77 had been knocked over by tractor, so set corner (1" sq pipe/cap) at 85.07 North of the N½ RP rod set 8-8-1977 and ~~[illegible]~~ W of S 33-34 as measured in 1977 and platted. Corner 1.90 So & road concrete on CR 10. 5273.16