1 8-20-69 set old geared car bumper jack staff in rock. #621906 de corner. (1)

1/4 corner West 1/4 19 Eyota 106-12

east 1/4 24 Marion 106-13.

6-1883 Hunter P384 no 375 L19 John Hughes.

corner gone but both B trees standing nrest corner, stone 2 x 6/15 x 24" from witness trees.

- set approx corner west at 9.98 at good chainage but est. line from E-W 1/4 line L18 L24 bad shape.

4-1884 Hunter P387 no 378 L24 Mahony Bros.

found stone P384.

established line west but destroyed it after survey so some parties wouldnt profit from work that didnt pay. (2)

6-1901 Robt Fraser P706 no 620 S24 J. Duly.
found stone P 384. tested B Tree
corner lies under fence a little north of fence
running east.
- 1/16 west drove stake M & L. to center 24 which
this time was set - a stake & stone & B trees.
10" Boak S17E 44 lks - 3" Boak N66¾E 31½ lks
Govt B trees W¼19 - 10" BO N87°W - 39 } Not B.T.'s given
12" " S81°E - 62 } in Govt notes. see card

8-19-69 J Kerr. Meas from fence south at center 19 2553.0 which
was approx record. - cont' west to prop. line & ¼ corner set 1883. 67.5
indicating corner lies 13.2' west of 2553. - found stone on R 658.3
slope 12" in ground and pried it together 2" x 6/16 x 24 leaning downhill
evidently by erosion pressure & show steep slope north - sharp drop south.

#621906

(2)

Card # 2 west 1/4 19 Eyota 106-12
east 1/4 24 Marion 106-13

soil has ravine with spring water and much erosion bounding 1/4 line on south for several hundred feet before breaking away to south. - Pushed line of old fence south bounding cultivated portion of farm believed to be part of old town line fence on 5 foot offset west. missed corner on west side about 1 foot.
8-20-69. Concluded stone found to be true corner - remeas. from stone to fence south at 1/4 corner or 9.98 west of org stone set 1883 P 384 - found at 657.6 R 658.7
tried to continue chainage west to Center 24 - found 1/16 fence over-

North at 668.5 from fence south at NW corner Jones lands.
-at 480' had to discontinue as creek erosion and brush had pushed fence line south 50' only way to measure line is careful offset south, then would be difficult. R Fraser 1901 spoke of brush & rough land in parts of NE¼ Sec 24. Agree
- set old screw shaft car bumper jack with gear case down in rock base as corner at W 419 org stone on S side big stone from creek on N Side many small limestones and 2 pieces Casting from water pressure pump. broken up (900 1968)
- Corner lies 1.5 west of 8" elm with long scar on W side
- 20 D S side blazed. 24" brook. 4' North of east 27.75
- 20 D SW side blazed. 18" to oak NW. 38.13.
line about 2' or less north of E-W fence - never was N-S fence at corner
total Meas east to Center 19 stake as found. 2569.6

#621906 (3)

1/4 CORNER West 1/4 19 Eyota 106-12
East 1/4 24 Marion 106-13

1/20/89 Roger Brand visited corner, did not find steel jack bar, found 2"x10" limestone top, top sticks up ± 6" but is leaning to the south Rp's limestone is ± 15' N. of center of small creek & ± 6' higher than bottom of creek bed. 5' N of E-W fence & 18' S of another fence which bows around on hillside above ditch. fd spike in 12" dead elm N.W. 19.7'. limestone is approx in line with fence south which ends about 150' South

#621906

(4)

¼ corner W. ¼ 19 Eyota 106-12
E. ¼ 24 Marion 106-13

Gov. Notes 1853 Oct. Ball, Dep. Sur.
North between 19 and 24.
35.53 Br..Oak 12 in.
40.00 Set quarter post.
Br. Oak 10 in. S85E 13 lks.
Br. Oak 14 in. N15W 64 lks.
40.72 Br. Oak 12 in.