X 4-6-73 set mark in bridge from West and east temp (1)
9-25-79 set corner M&L #622606

1/4 corner 26-27 Eyota 106-12.

5-1902 W Fraser P14B & 26-27-34-35 5 parties see N 1/4 26.

Corner lost, set stone 4x6x20 M&L 39.85 2630' N 30' W.

-1/10 south set stone 3x10x22 M&L 19.92 1/2 1315.05 11

-1/16 north set stone 3x8x18 M&L 19.92 1/2.

-1/16 west set boulder M&L 19.94 1/2 1316.37 N 89° 53 W

-1/16 east set stone 2 1/2 x 7 x 12 M&L 19.89. 1312.74 S 89° 40 W

-1/16 center SE 1/4 27. set boulder at inters lines

-1/16 center SW 1/4 26 set boulder 4x5x14 at inters lines

(over)

11-1961 Minn Hwy Dept DuVal.
set 3/4" iron rod - assumed corner found nothing
MH D disc cor F Post E 48.94.
" " W 11.35
" Cedar tree NW 37.7.
DuVal Meas north 2633.45 .84 } 5261.6.
south 2628.15
Record. W Fraser. 26.30.1 M & L.

---

8-1934 CoHD B53 P64 found recorded stone, removed and laid on fence line went to be replace after grading.
- corner lay. 20.3' west of E PI and 1.5' north of
RP marked cedar NW 36.3 - Hub on fence line west 33.0

Card # 2. 1/4 26-27 Eyota 10 6-12. #622606 (2)
9-6-73 ran aerial from. 1/4 27-28 direct over
Center 27 as set. 6-7-73 - set prism there - found
1/16 post remains. at: 1316.79 R. 1316.37 5-1902.
set 3/4" iron rod at 1/16 on W side post exact line above.
Came in center post as to N-S. doubled meas for.
1/4 26-27 made mark in bridge for corner temp.
RP 1/16 9.2 N to woven wires & N I 90 R/W fence
20.0 NE to E edge post & no access I 90 post
- meas E to Center 26 found. 2625.75 E. R 2625.48
then. 2643.15 from center 26 to limestone at 1/4 25-26.
R 2641.98 WF 5-1902 which fell .2 S of line. so
mark on bridge may move .2 N.
- meas S to SW 26 where it ended at 2628.94 including .2 N.

RPs to 1/4 26-27 and what set as corner. when set
Meas of E-W mg to inside face of bridge curb 4.58 ±
May be raw line before final setting and RP north beyond
normal bridge expansion.

---

Set by William Jones 9-1853
40.00 Set post at qr. sec. corner
Br. Oak 4 N 34 E 84
Red " 5 S 61 W 50

9-25-1979 We set this corner M+L after comparing the location with the line from the E. 1/4 Cor 26 and Center 26 which came 1.29 So. of midway. Since the corner falls on the deck of the I-90 bridge we could not set a monument so we set a RR spike (with punch mark) 50.00 North on the section line as an R.P. The 1/4 Cor itself came appx 17½ West ℄ and 10' South of the expansion joint at the north end of the bridge. The RR spike R.P. is also 17½' West ℄ and appx 40' North of the expansion joint at the North end of the bridge.

#622606 (3)

1/4 Cor 26-27 Eyota 106-12

RP's to punch mark in RR spike:

① 5/8" rod behind West curb appx 7' North of expansion joint @ North end bridge deck S5W 33.47
(This ties in 17.72 NNW of 1/4 Cor.)

② 5/8" rod behind East curb appx 3' North of expansion joint @ North end bridge deck SE 54.66
(This ties in 42.32 NE of 1/4 Cor)

5-16-97 FOUND RR SPIKE RP IN GOOD CONDITION. 17½' W OF ℄

(622606) ✓

6-25-99
MW, RF, AE

49

1/4 Cor 26-27 Eyota 106-12
Found R.R. Spike witness Corner
to 1/4 Cor 26-27 42' North of
End of bridge over I-90

Set 1" sq. pipe w/Cap East of
East guard Rail North of I-90
Bridge 35' East of ℄ CR #7
and 135' South of So. Edge off Ramp
Concrete

TC Ref pipe
ART Sta. (BEAR) to witness Cor

241°52 42" dh03 | 243°20 29" dh02
0°01'43" dh00 | 1°29'20" dh00
241°50'59" | 241°51'09"

To (BEAR) (Brass disk in Conc. Cyl.
VA 89°59'55" dv00
Slope 904.490 Hor 904.49
To witness Cor (RR. spike)
VA 88°03'15"
Slope 62.20 Hor 62.165