X 6-8-1973 set CIM over iron rod (1)
cor'd 3-11-75
#622706

1/4 corner 27-28 Eyota 106-12

5-1896 Hunter P600 No 545 S28 H^m Busian

corner missing, B tree gone, set boulder stone 10x12x18

M & L 39.93 1/2 N 1/2° W 2635.71

5-1902 H Fraser P14 B S26-27. 5 parties see N 1/4 26.

found boulder stone P600. Took Birch 9" burr oak W 54 lks N 3 lks

---

7-1939 J Kerr P488 B S28-29-32-33 Town Board.

found boulder in place in line fence east

→ 26.35.26 north and south To sec cors.

over.

11-1961 Du Val Minn Hwy Dept.
found boulder 2.5' deep set 5/8" rod riser.
Disc in F post E 45.2
Disc in PPole NW 43.3
Disc in F post W 34.75
Disc in tele pole SE 72.2

7-30-1968 J Kerr found iron checked references
new RPS. - Minn Hwy Dept Elevation bench center - E - 69.73.
NW - Disc on NE side new 6" cedar corner post 58.5
6-7-73 dug with tractor at 21-22-27-28 and found
true corner then ran N-S line betw 27 and 28
found meas to be M&L 2636.36 Hunter 2635.7 - J Kerr 2635.4
- found iron at 1/4 27-28 to be very close. set
C/M at this point a new true corner
Lee Card & 2 RPS.

Card # 2. 1/4 27-28 Eyota 106-12. (2)
#622706

58.43 N W to disc in 6" cedar post.

70.14 E to MHD elevation bench center mark.

49.85 NW to 3/4" rod in 8" round. MHD Concrete RP Marker.

50.35 NE to same type as above.

35.65 WNW to center RR spike driven in PP 40390

88.6 S to N edge west bound conc roadway.

Gov. Notes Oct. 17, 1853
North between section 27 and 28.
Var. 10° 20' E
2.00 Enter timber Br. Oak- bears N.W.
23.75 Br. Oak 8" diameter 40.00 Set post at gr. section CORNER

(OVER)

Br. Oak 6 S 10 E 54
Br. Oak 6 S 25½ W 54

May, 1856 Thos. Hunter Pg. 6 No 10 shows 1/4 Post.
1/16 East 19.99 chs. M&L - 2 B.T.'s (N 49¾°E 405 lks. & N 31¾°W 324 links.)
1/16 North 19.91 chs M&L - 2 B.T.'s (S 57¾°E 441 lks) & (S 51½°W 329 links).
Meas. South 39.80 chs. to Sec. Cor.

April, 1863 P.C. Compton Pg. 69 No. 97 shows 1/4 stake used to set Center Sec. 28