#623504 (1)

S. ¼ Cor. Sec. [redacted] 35 Eyota 106-12
Gov. Notes 1853 Oct. Ball, Dep. Sur.
40.00 Set quarter post .
Br. Oak 8 in. N32W 186 lks. 122.76
Br. Oak 7 in. S8W 36 lks. 23.76
45.20 Brook 3 lks. wide runs south.

April, 1863 B.C. Compton Pg. 68 No 96 shows ¼ stake used to set Center 35 at Intersecting Lines.

4-27-81 1/16 East! Dug in line with the fence North & South and from 20' to 28½' North of the traverse iron set East of the fence. Dug to just North of the center of the road. Poor condition, 1' to clay.

4-15-81 S¼ Cr 35: Visited corner area. Found possible SW bearing tree stump - a 24" Oak. Cut to the center of the stump. Found a scar that could have been a blaze but could not prove this to be the Govt blaze. This was a large black area - possibly charred. The stump would place the corner about ½' South of the E-W fence on the South side of the road and 10.61 North and 8.61 West of the computed corner location at the intersection of the line from N¼ Cr 35 over the Center 35 and the line from SW 35 to S¼ Cr 36.

4-28-81 S¼ Cr 35: Set a CIC/4' square pipe as the corner at the intersection of the line from the N¼ Cr 35 over the Center 35 (Spike on corner fd 1975) and the line from the SW Cr 35 to S¼ Cr 36 (as set 1975). The corner lies in rough sidehill and 12' South of E-W fence on the South side of the road

(continued)

#623504 (1)

South ¼ Corner Section 35 Eyota 106-12

4-29-81 continued! Set a survey marker sign and post 1.2 South. We decided not to use the stump we consider a possible bearing tree since we could not prove it to be one and because it would have pulled the corner 50 feet West of the line from the N¼ Cor 35 over the Center 35.