X 11-21-74 - Set a 1¼" pipe as the corner in concrete C.R. # 7

#823506

1/4 corner 34-35 Eyota 106-12

5-1902 W Fraser P14B & 26-27-34-35 5 parties see N ¼ 26.

found boulder on line sec corners

Meas north 39.98 N 45° W 2638.68.

Meas south 39.94 2636.04

49 lks north and 32 lks east of tree.

8-27-79 Set a small punch hole at this corner on W. Fraser's prorated meas. N ½ = 2638.58'. S ½ = 2635.94'. mile = 5274.52

R.P.s: Punch hole top lug bolt 24" e.m.p. (S. End) S.W. 56.52

Punch hole top lug bolt 24" e.m.p. (N. End) N.W. 62.07

Punch hole is in pavement, 0.18 west of crack

(over)

1/4 cor 34 - 35
Gov. Notes Oct. 17, 1853
North between sedtions 34 and 35
Var. 10° 19' E
40.00 Set post at gr. section corner a20
Br. Oak 8 S 17 E 66
Br. Oak 8 N 82½ E 63

April 1, 1863 P.C. Compton Pg. 68 No. 96 1/4 stake Gone - Reset midway & on Line between Section Corners used to breakdown N.E 1/4 34 & N.W 1/4 Sec. 35. (Set Stone as Corner)

5-16-97 FOUND 1¼" PIPE IN GOOD CONDITION 0.2' W ℄ CR #7
5-23-97 SET 1" SR PIPE/CAP AS REF ON N EDGE 55TH ST SE.
10½' N ℄ 55TH ST SE. 151' W ℄ CR #7

(623506) ✓ 6-25-99
MW, RF, AE

52
1/4 Cor 34-35 106-12 Eyota
Found 1¼" Pipe 0.2 West of ℄ CR #7

TO Ref pipe Set (5-1997)
Set PK in PP# 48979 (pole in SW
Cor Int CR #7 and 55th St to
1/4 Cor 34-35

342° 36' 06"	344° 19' 54"	
0° 41' 08"	2° 25' 00"	
341° 54' 58"	341° 54' 54"	

Set PK in PP# #8980 (2nd pole West
of Corner on South side 55th St.
to 1/4 Cor 34-35

193° 30' 56"	195° 45' 40"	
0° 43' 20"	2° 58' 08"	
192° 47' 36"	192° 47' 32"	

TO 1/4 Cor 34-35
VA 89° 51' 42" dv 04
Slope 151.39 hor 151.39