#630104 (1)

5-27-64 set C/M over iron M&L 2639.2

~~6-5-80 could find C/M Mc with brass cap set at E 1-12.~~

6-16-87 set CIM / "Corner of Cmty"

1/4 Corner Cert 4-15-75 Marion 106-13

12-1910 Ch Larson P142B. L 12. Rebar, Iron Pipe + chiseled found boulder as 1/4 corner. no desc, no history of any kind of corner.

- meas of 1168' shown from corner south to R.R. tracks
- meas shown of 40 chs east, west and south.

---

6-1962 J Kerr B85 P45 could find no corner on could be wrong extensive digging set Corner M&L 2639.2 See card 2 2.

note some question as to northing & southing of NE cor 12.

B89P69 1/16 corner south M&L 1316.37

B90 P54 angle in SW Quadrant 90°41'

(over R.P.'s)

C/M has iron rod below.

center spruce tree SSE ~~47.2~~

Dice in power pole SE ~~49.7~~

Corner lies 3'± west of fence south Rod 33' south.

in layout of lot 350' x 475'

11-5-1970 Co surv. corner in question, having never been found after digging 4'x6' at east 1-12 Marion and finding stone which was not absolutely positive but very likely. Also probed 4' in all directions. accepted stone as corner until proven otherwise - pulled C/M in place (broken) and placed corner. See Card.

C/M over 3/4" x 12" rod, could find no rod below present C/M.

- moved corner 3.35 North and .45 east

RR head & large nail on NE side PPH 21427 SE 47.31

- 40 D in W side center most nearby pipe up 2' 8'E & S. 50.28

- hard nail in small knot in NE side tele pole up 3' NW 47.89

- corner near average center road. some 3' W of fence South

#630104 (2)

Card # 2 1/4 1-12 Marion 106-13

11-5-70 Co surv. new C/M as set is midway and line from. NW 12 and stone found at NE 12. 2639.65 OK RO - & E 1-12 would be set in center road as recorded and overed by farmer. Liberg by corner as still true center and midway between proven E 1/4 12. (.17' south deed line W 1/4 12 and Center 12, both authentic corners used in 1910) this midway (total 5280.17) would bring E-6-7 north 4.6' (2640.17 - 2635.57) corrected N-S meas. this 1/4 1-12 would still go 2.3' further or 5.65 N of 1st C/M which would bring Larsons' meas to R Railroad 4. 1168' within 2' - B 90 P54 Surv Book for P Rubow in NE Cor & NW Cor Sec 12 - RR & meas 1160.07 - 5-28-1964 B 89 P29. believe this first time ever used C/M at 1/4 1-12. run line after setting E 1-12 Marion set corner. M & L. 2639.2 angle west to south 90°41'

SEE Blue Book For dig @ 1/4 Cor 1-12 1/16 2 — OVER.)

1/16 South B90 P54 Meas only 156.3 N to ℄ RR - 207.19 N to fe. N Wire
- B89 P69 Earl White run line center 12 north to orig CIM at 1/4 1-12
total 2632.74 - 1/16 corner in N road ditch of conc highway in line
fe. N mar W end field drive culv. 1" drift pipe. No RPs.
- Note Change in 1/4 1-12 11-5-70 .45 E 3.35 N - May change
again if E 1-12 Change to ℄ road N & L 1/16 corners
as now 1/16 shoved go .225' E 1.675' N
Govt Notes 1853 Wm Sones

40.02½ set post or granite survey corner. Disposition
handled at Chicago & made record [illegible]
[illegible].

---

7-8-82, 1/4 Cor 1-12: Dug from a point 4' North of the ~~CIM in place~~ Taylor pipe location (M℄L from Ken CIM @ 1-2-11-16 to boulder Fd @ E. 1-12 3.92 N & 1.30 W of Taylor pipe). Found a pointed boulder (top down 2') with 5"x9" base 11" long standing on crushed rock laid right in clay subsoil. This stone 4.34 North and 4.55 West of iron rod over CIM (Note: someone pulled T-T pipe so we put large iron bolt in pipe hole) (Continued)

#630104 (3)

1/4 Corner 1-12, Marion, 106-13

7-8-82, 1/4 Cor 1-12 continued: Projected the fence from the South and it came 10' East of the stone found (or 5½' E of CIM). Fence from ~~South~~ North came 9' East (or 4½' E of the CIM)

5/12/87 DUG FOR CORNER (SEE R 1987 EEMON. BOOK)
6/16/87 SET CIM OVER ½" RE-ROD IN LINE WITH FENCES N & S AND IN E E-W RD, CORNER 4.50 E OF ¾" RE-ROD SET OVER CIM (15" DEEP) – REMOVED BOTH RP's CSD IN NE SIDE PP# 21429 SE 44.12
CSD IN SE SIDE E ly GATE POST NE 39.21