3/13/89 SET 16" CIM OVER OLD CIM
5-23-63 set CIM over iron rod

#630504

1/4 corner. 5-8 Marion 106-13.
Probably T. Hunter

Corner gone - replaced N&L.
-16 east set stake N&L. 19.96 1/2. (1317.7'
-16 west set stake N&L 19.96 1/2 (1317.7'

---

set CIM in place of iron rod used as corner.
- Disc in power pole. NE 124.9.
- Disc in power pole NW. 149.7

Govt Notes Wm. Sims 1853

5271 Set post a quarter section post, depression
chiseled, mound raised, pits
planted thereby bears W. E. - S.W.

1932 - C.H.D. Book # 64 Page 75

New Ties to + on top of stone 9-2-38 A.A.
S 1/4 Cor. sec 5 - 106-13

Button in Tel. pole N.W. - 42.3
" " Tel. pole S.S.W. - 111.6

(Possible wrong Corner Could be sec. 35)

3/13/89 DUG DOWN 18" TO CIM IN CO RD. 144, SET 16" CIM FLUSH IN BLACKTOP, E OF GOLF COURSE DRIVEWAY WEST 80.0'