9-13-65 set CIM over. ½ '×2' rod reset by Co H.D. 1968

#630506

¼ corner 5-6 Marion 106-13.

6-1896 Hunter Dep & S. P603 no 548 L6. Halbert, Col. Brackenridge.

Corner gone, found remains of old corner post which Mr. Leo Cook knew was where old stake stood.

-16 west set stake N&L 19.85 (1310.1

5"×13"×16" limestone with cross. west of old corner post remains with glass and crockery. used as cor.

- 1965 CIM set to preserve corner.

- 1966. Junior college grade made. corner graded out.

New corner. Iye painted steel post beside corner, corner lies in road ditch Cover M'Ghie

Co HD B316 1966 - replaced C/M. after grading found rod. - likely rod placed below C/M. 9-1965. C/M gone re-set C/M. again after final grade.

Center road lies 54' west of corner. used to be east of corner entirely. corner found easily now - steel post witness.

11-10-72. Ele Meas from C/M found in east ditch direct to nail set 50' west of County replacement of N 5-6 Marion.

See McGhie & Betts Survey of Sec. 6-106-13 in Notebook file.

7-1979 Shot Corner in Control Survey

Good Notes Wm Jones 1963

58.78 St post at quarter section corner

Book 15 55 E 337

And more found

(5)

3-2-11
EMA JTJ BB

"630506" C 1/4 COR 5-6 106-13 MARION

FOUND 1" SQ PIPE/CAP DOWN 0.5' IN GOOD CONDITION ON EAST SHOULDER OF NBL CSAH #22. CORNER FALLS 2' E OF EAST EDGE BLACKTOP SHOULDER. 22.3 E OF ℄ NBL CSAH #22 + 88' S OF ℄ RCC ENTRANCE

CHD IN PP #23138 SE 63.66'