X Corner falls on San. Sewer M.H. — must have RPs to set.

#630606 (1)

1/4 Corner west 1/4 6 Marion 106-13

east 1/4 1 Rock 106-14

6-1896 W Fraser by Hunter P603 no 548 26 Hulbert Bracebridge

Corner assumed to be corner fences running north & east

- meas south 39.86 = 2630.76
- meas east 38.54 = 2543.64 — 18.64½ - 19.89½.

---

pipe now in place as corner — no RPs

See more dope M.C. & Belts was conc mon. now Manhole.

modern R.P.s —

Govt Notes. Wm. Jones 1853

40.00 Sec. quarter section post
15 in. oak 14, N 3 = W 244 lks.
Log trench.

#6306006 (2)

West ¼ Corner 6 Marion 106-13

East ¼ Corner 1 Rochester 106-14

Check T.H. City Surv.: Did not set stone @ this corner.

City Info.: Corner on manhole cover at intersection of 4 marks in ring.

11-29-77 Tied out corner since street being graded. Drove ¾" x 30" pointed shaft 2½' S. of S. edge of 32' Cottonwood SW 56.18. Occupied rod and turned an angle left of 57° 10' 35" from most southerly SW corner of westerly of pr. of dorms on RCC campus (Loomis)

11-7-84, W'46: 7d 2 set of chisel marks in manhole ring. One set large mark and deep. The other set smaller. Used smaller set for point shot since it

tie to RPs iron SW. Large marks intersected .12 NE'ly RP's:

PK nail in curb joint near top NW 25.44

PK nail in curb joint near top SW 26.03