#631105

(1)

section corner 10-11-14-15 Marion 106-13
See also Bk 9 P. 1-3 for same info.
6-1898 W Fraser. P631 No 571 S 14. G Marquardt.
could not find corner. big area dug up as though
search for corner had taken place. found what appeared
as stumps of IVE, SE and SW Blues which placed
corner 3 rods east of corner of fences. in line fence west.
This seemed about right for meas east (not given)
- set no stake or corner.

---

see Kerr Book 26 P. 60-62 1941 Survey
iron pipe ~~in 4 way fence corner~~ accepted as
section corner. well above ground. (Pipe is East of ? Fe Corner)
NW cor sportsman club - SW cor John Winter 40 A.

over.

12-1941 - J Kerr B 26 P 60-62. A Peterson.
Meas S¼9 to ¼ 11-14 set ⅜" pipe 7892.94 from S¼ 9,
2630.27 from N¼ 14
- meas NW 11 to SW14. set the pipe 3/4" pipe Midway. 5266.43
- set ¼ 14-15 pipe M & L 2633.21.

B51 P54 Meas south 1414.1?- 1425.63? To ℄ Road

Analysis of Corner location appears that J. Kerr attempted To set corner by double proportionate measure. and ignored the fences in place (also possible monument if any) - it appears his corner may be Too far North by a few feet and Unknown location E-W — hard To figure his measurements on the 1941 Survey (BK 26 P. 60-62

Zenk Engr. (Tom Veenker) 4-1977 - " per Conversation with Roger Brand, John Kerr used 4-way fences. Found a Tree with fences coming out in 4-directions. Set ⅝" Pin at this location.

Sales Co. 10-11-14-15 Mar. 10C-15
#631105 (2)

Geo. Wm. Wm. Jones. 1853

50.00 Sec part - acres 10 cut 10, 11, 14, 15

Bk. Ork 13 N 24 E 36

" " 8 N 48 W 63

" " 6 S 52 W 41

" " 6 S 12 E 47