8-4-1969 found C/M reset by Co Hwy Dept (1)
~~slant pipe Aver in~~ new black top.
5/14/89 REMOVED PIPE, TO CHECK C/M #631505
section corner 15-16-21-22 Marion 106-13
no records - 1" pipe set in stony grade of road.
all RPs ~~Sp~~ 16" oak stumps
Sp power pole
Sp " "

E	36.55
SE	34.33
NW	49.70

½" rod on transit line to knot in top light pole in yard slightly east of due northeast 150'

5/14/89 FD BRASS WASHER WITH NAIL IN E OF C.R. #11.
FD ½" PIPE DOWN 0.3'
5/18/89 REMOVED ½" PIPE FD C/M, CHECKED OLD CHD DISC IN P.P. SE 61.57', OTHER OLD P.P. TIES GONE

9-1963 B87 P43 run line east to ¼ 15-22.
set stake M & L 1318.25'

Co H.D. B 281 1963 found 1" pipe PI Δ 0° 4' lt going N.
Meas south 2637.37 To ¼ 21-22
Meas north 2635.8 To ¼ 15-16

Govt Mon. Wm Sess 1855
50.00 S. of ¼ post of Sec. to stat. 15-16-21-22
Bur. Oak 8 N 7 E 606
" " 9 N 25 W 6
" " 8 S 22½ W 44
" " 5 S 22 E 35
10/10/62 CHD (bk 281) RP's
Spike & disc in top of corner post east 61.54'
Spike & disc in P.P. ESE 61.55'
Spike & disc in 30" oak ENE 75.57'

SECTION CORNER 15-16-21-22 MARION 106-13 (2)

JUNE 1994 FD CIM 6" DEEP. SET REF PT 1" SQ PIPE W/CAP W OF COR NEAR TOP OF HILL. #631505

T @ REF PT.

4RT RK NAIL IN PP. 2ND POLE S OF COR E SIDE OF CR #11 TO SEC COR 15-16-21-22

15° 52' 54" dh 06 — 308° 07' 54" dh 06

80° 52' 12" dh 02 — 13° 07' 16" dh 05

295° 00' 42" — 295° 00' 38"

TO SEC COR 15-16-21-22

VA 98° 01' 37" dv 01

SLOPE 66.53 HOR 65.88

11-16-94 CHD SET 1" SQ PIPE W/CAP