#6326060 (1)

5-29-1962. set C/M over 3/4" iron, set previously.

1/4 corner 26-27 Marion 106-13.

6-1892 Thos Fraser P492 no 466 L27 v J Dick Dunnett.

Could find no trace of corner, in road, B tree gone.

set temp point M & L 39.85 (2630.1 for line west.

5-1940 J Ker B20 P33 L27 J. O'Neill.

Run & meas line betw. 26-27 5261.74

set point midway 2630.87 and corner at 3946.26 for line west.

6-1951 J Ker B51 P68 L26 Leonard Leitzen.

run N-S line as in B20 found W 1/4 26. set 3/4" iron bar.

-16 north set 1/2" iron M & L 1315.55

(over

-16 south set or found 1/16 cor of B 20 for line east.
-16 center NW 1/4 26 set budge bolt M & L on E-W 1/16 line
1317.95' -16 center SW 1/4 set M & L on E-W 1/16 1315.97

5-1962 placed C I M over rod in place.

Sp	power pole	WNW	30.3.
Sp	tele pole	NNE	67.5'
SRP	fence post	SE	46.41.

line in center road - no fences E & W.
road graded. 1968 - corner left in, graders warned of corners
presents. very little fill or cut seemed likely at this spot.

1/4 corner 26-27 Mining 106-13 #632606 (2)

Cook Notes, Wm Sims, 1853

40.00 Set post of gum corner

Bur Oak 6 N½ E 7½

Bur Oak 6 N½ W 6