#633104 #1

X CIM set 1977
9/29/78 CIM set 1978 "Correction"

1/4 corner south 1/4 31 Marion 106-13

North 1/4 6 Pleas Grove 105-13.

6-1892 Pr Fraser P502 No 472 Sd J O'Neal J Burns M Angus

found boulder in center road placed by Mr. J O'Neal when govt stake stood plainly 6458.1'

– south set stake 9.78 1/2 for prop line west – then

1/16 south set stone and stake M & L 19.919 (1314.65 for line east.

both on line to stone at center 6 set by inters lines.

from above 1/4 cor southwest – 645.8 then 668.9 – then 1314.7

– Center section 6 a stone set at inters lines.

over.

1966 J Kerr

run line for grading 1½ mile road. corner believed gone and heavy cut in that area did not dig as both section corners in, road straight on town line corner would have to be set on town line and intersected by some kind of line from south at proper place.

1952 B55 P17

Near north line sec 6. 5208.9

Near south line 31 - 19.40 - 20.00 - 20.00 - 20.00

1280.4 - 1320 - 1320 - 1320 - 5240.4

1272.58 1312.11 2624.21. - 5208.9 - 5-1952 B55 P17

7-12-77 Dug with backhoe to clay and bedrock 8'x8' + 2½' deep. Found nothing.

7-28-77 Dug further N to cover [redacted] location at which corner will be set. Found nothing. Set CTM over a ½" x 2'

1/4 Corner — South 1/4 31 Marion 106-13 #2
North 1/4 6 Pleas. Grove 105-13
#633104

(cont.) rod on line from the 5 1/4 Cor Sec 6 over the 1/16th N of Center 6 and at double the measure of the calc. Center 6 over the 1/16th N. Corner 10' N & E-W road and in line with the main line of the fence So.

R.P.s: CSD in pp # 37961 NE 78.24
CSD in corner post So 43.18
Punch hole top E end CMP in direction NW 49.97

W.F. PPOP. COR. Set 9.78 1/2 chs. So.. No good
7-77 found 1 1/2" x 7" x 18" limestone (up 6") on S.E side of corner post to fence N and W
7-77 dug from 4' to 7' N of stone and 4' E-W to cover W.F. measure from 1/16th So (found). Found nothing

9-29-78 Set a CIM over a ½" x 2' rod 7.02 So (on N-S ¼-line of Sec. 6) of CIM set in 1977 (removed). The corner is 3' N. of ℄ and 1' E. of fence So

RP's: CSD in pp# 37961 NE 80.78
CSD in C.P. S 36.23
Punch hole in top E. end C.M.P. in field drive N. NW 52.79

After finding the 1/16th N. of ¼ Cor 5-6 @ prorated Govt measure instead of midway as recorded by W. Fraser we believe that this was also the way he intended to set the 1/16th N of the Center 6 instead of midway as he says. Therefore, the N. ¼ Cor 6 is now set at Fraser's measure from the stone found at the property corner he set 9.78 ½ chs. South.

1/4 Corner South 1/4 31 Marion 106-18 #5

North 1/4 C Pleasant Grove 105-18

Govt Mon. Wm Sons. 1853 #633104

40.00 Set post in ground mod. rocks

Bearing S N 90° E 21

" " 12 S 35° W 13.1