6-16-1964. set CIM at proper slightly relocation of orig. Note: Corner now incorrect 10-1981 cor.

1/4 corner Center 28 BK 13 PG 72-73 Rock 106-14

T.H. 1856 - Plat and T.H. 10-14-1878 Sec. 28

~~no records~~. See T.H. Book 5 p 88 for details. #642809

3-1958 J Kerr S 28 E Dody B66 P 68.

run E-W 1/4 line. set center at intersection, a pipe.

set 1/16 rod west 1326.07 M & L

set 1/16 rod east 1320.35 M & L.

- meas south 2637.67

Note: This Corner probably Not Correct as S 1/4 corner 28 should be shifted East ± 12'-14' To on line from Sa

Since S.W. Cor. 28 was in error by ± 11' - R.B.

10/3/89 FD CIM JUST WEST OF WOOD POST

one CIM

6-1964. J Kerr setting corners.
set C/M in place of pipe
1" pipe some above ground. S. 0.6'
Center blazed 20" burr oak NE 7.6
" " 16" " " NNW 19.0
Corner was slightly shifted from pipe set 1958
due to survey east side 2'8 later. less than foot.
in fact pipe reference 0.6' S. was orig corner. 1958.

June, 1856 Thos. Hunter Pg. 11 No 17 shows 1/4 Post with 4 B.T.'s
B.T.'s To Center (N 52 1/4° E 19 1/2 lks.) (N 24 3/4° W 50 lks.) (S 19 1/4° W 27 lks.)
(S 37° E 21 lks.) Survey of E 1/2 N.W. 1/4 & W 1/2 N.E. 1/4
1/16 West 19.58 chs., 1/16 East 20.04 chs., Meas. North 40.18 chs.,
N-S 1/16 line in N.W. 1/4 meas. 39.81 chs., N-S 1/16 line in N.E. 1/4 Meas. 39.82 chs.