11-27-1963 set C I M over pipe. #643504 (1)

¼ corner south ¼ 35 Rock. 106-14.
North ¼ 2 Ht Forest 105-14.

2-1872 Hunter P193 No 204. S2. Chas Carroll.
Peter McCluskey.
corner gone, reset stake from 2 B T stamps cut below
marks Qut proved correct by govt bearing & meas.
No meas pertinate as centre section changed P294.

2-1876 Hunter P294 No 289 S2. Chas carrol
E Mountain.
- meas south now. 39.64 against 39.22 in P193

---

a 1¼" pipe used as corner many years assumed correct.

4-1903 R Fraser fieldbook #10 P16. Corner post of fence.
meas south to stake 39.79'2. (2626.47 (over

1-1963 J Kerr.
placed CIM over pipe driven down.
Sp power pole LE 82.0 GONE 1987
Rec corner fence post S 37.4
fence running north E 2.0
corner Rec just south center Main road west.
- west ½" rods driven on section line at following stations
907.4 — 1064.42 - 1511.77 - 1800.00
2262.43 - sec cor NW 2 sta 2610.2
also rod on sec line at ℄ proposed road south -?

March, 1857 Thos. Hunter Bg. 22 No. 35 used ¼ corner to set Center Sec. Meas. North 40 chs.

1/4 corner South 1/4 35 Reference Iron
North 1/4 2 N. Fence Iron

(2)

Govt Mon. found. 1854 #643504
40.00 Dist post to 1/4 Sec. corner
Brook 10 W 80 E 275
Brook 10 S 40 W 120

9/22/89 REMOVED 8" BENT RISER FD CIM CHECKED ONLY RP LEFT
DISC IN FENCE POST S 57.31 (1963 37.4)
9/25/89 TOOK NEW RP.
79.48' SE TO CSD IN PP # 44260
7/2403 Robert Fraser (Pg 712, No. 625½) Used corner post Mr Fulton avers that C.P. was put in place of old stake, another old settler avers to the same chained south 39.79½ to corner post that also was 2 avers in place of stake