#650305

1 11-11-69 set C/M over pipe by line & meas from south
9-4-73 C/M removed & placed correctly.

section corner 7-8-17-18 Salem 10 6-15. (1) 3

5-1893 W Fraser P 508 No 497 S. 18 Severto, Christian Isaacson.

Corner gone for many years.

- Meas SE 18 to W¼ 8 where stone was found in place set by Hunter line short 18 links ⅓ = 39.94.
- Meas NW 18 to NE 17 where stone was found in place set by Hunter. line meas short 35 links. which with govt prop. placed stone 6 x 9 x 15
- Meas north & south. 39.94 2636.04 6" brook S 82½ W 63 lks
- Meas east & west 39.91¼. 2634.22
- 1/16 west set boulder M & L 19.95⅝ to boulder set this survey

1317.11

over)

5-1893 W Fraser P610 no 478 S17. Jacobson, Johnson Anderson, town board

found stone P508.

Meas south 39.94 to 2636.04 stone P508.

Meas east 39.87½ to 2637 stone set in place of stake found.

7-15-69 J Kerr Meas & run line from SE18 north found ¢ stack top at 2637.15 and fence line east at NE18 at 5263.35' R 52 72.1 – set tard nail in line fence east = 37.7' E to fence staple on PP 39194 holding fence corner brace wire.

7-17 J Kerr found ½" 7-18 pushed line over ⅛ stone found day before at 1317.0 R 1317.11 dug hole 2' dia 2' deep probed 5' deep but nothing set ½" x 3' rod no ref. Rod corner. 1.37' west and 1.76' south of nail set above. or 5261.6.

7-18 found ⅛ stone 1316.6 R 1318.0 north of SE cor 18 projected line ac 7-15 only a few hundreds diff much mirage –

see card 2

#650805 (2)

Card # 2 Section corner 7-8-17-18 Salem

7-18-69. after projecting line dug north and east of digging of 7-17. found old road at 4' hard to probe. abandoned. will bring tractor. - left rod set on line from west at 1317.0 and direct line set 7-17. - also set rod on line from south about 1.35 east and 1.75 north, exact line from SE18 over 1/16 stone found and 5263.2 north of SE18 - line as former reference about 37.7 east of staple in power pole and on line fence east

- true corner of 4 times 1316.6 would be 5266.4 or 3.2' north of fence east. - 1/16 stone west was laying flat but squared corner have been set that way. If erected would come close to old rotten post 2' deep and glass bottle some 1.5'± north which would set NE18 at proper distance from South.

11-11-69. dug with tractor to clean clay 4½' deep. found washed road bed at 4', dug north beyond record meas 4' north rode and 3' east of rode. no possible chance corner could still be in ground. impossible to probe, undermined with bar. Set C i/N over 15" ½" pipe with part of union on top at exact point of line from south. this would make 1/10 rod west, .87' too far south and .67' too far west.

- Measurements - SE 18 to 1/10 slow north 1316.6 4 times 5266.4 set corner at 5263.2 as compromise as record would throw way too far north for 1/10 west. Considered a fair medium asset.
- pepsi cap south side power pole 39194 E ~~37.73~~
- 20 D in hub east side blazed 20" oak SW ~~62.5~~
- 20 D in hub south side blazed 14" br oak.
- the southeasterly of 3 trees likely suckers from orig B tree S 82½° W 41.58. 3' S of W ~~41.0~~ record 3

corner barely south of fence east - 4' east to center road.

#650805 (3)

Card # 3

7-8-17-18 Salem 106-15.

10-1-70 Co surv. found stone at 1/4 17-18 3.5' below black top road 3.63 south of Q which - came 2633.52 North of 17-18-19-20 and found at .36' west of orig line SE 18 over 1/16 stone north 1316.6

R. 1318.0 midway now would be 1316.76

- present C1M at NE18 above on orig line at 5263.2

- C1M should more west .72' and 3.84 north

- 1/16 iron west set at 1317.0 by post would go E.68 and N.88 to be on line C1M as is. or 1317.68 M&L chen

- if C1M moved as above iron will go .68-.36 or .32 E and .88 + 1.92 N or 2.8' north (very near old post found 3' deep?

OVER.

New RPs. CIM pulled and moved .72W 3.84N 9-4-1973

- pepsi cap S side PP # 39194 - E 38.52 38.60
- 20 D in hub E side blazed 20" brush - SW ~~57.5~~ 55.42 (7-80)
- 20 D in hub S side blazed 14" brush which is southeasterly of 3 trees likely suckers of orig witness tree (S 82½° W 41.58) - 40.77 Good 7-80
- good fence running east main line. S. 3' ±
- Meas north to ¼ 7-8. 8-28-70 CIM to fence E 1322.7 CIM to nail & rock W 2644.0. exact EW ¼ line 7-W ¼ over center of ¼ stones came 3.82 S of 2644.0.
- If CIM at SE 7 goes 3.84N and E ¼ 7 set on E WO ¼ 7 prop Meas would be 2636.34 R. 2636.0
- Meas then SE 7 to SE 18 52-67.04 or 2633.52 M&L.

5-6-71 Meas east adding .72' to allow for setting CIM west tole found mon at 2630.85' R. 2631.75 (Sta 12+16 quite steep) and accurate levels could allow this shortage. above setting acceptable.

#650805 (4)

Section Corner 7-8-17-18 Salem 106-15

Set by Michael Karrick 6-1854

80.00 Set post for corner to sections 7, 8, 17 & 18 erected mound with trench, pits, charred stake and Osage Orange Seeds at each angle.

7-14-1980 (1980 Lemon BK) Retied corner before road grading. Checked old R.P.s:

O - pepsi cap in South side ppt#39194 ESE 38.60

-20d in hub on East side blazed 20" Burr Oak SW 65.42

-20d in hub on South side blazed 14" Burr Oak WSW 40.77

— New RP's —

Spike and CSD So side 14" Burr Oak West 73.70

Spike and CSD NW side 8" Burr Oak SW 60.40

Before road grading this corner 6' West of center of

road and 3' North of fence East.

(650805)

11-9-99
MW RF

Sec Cor 7-8-17-18 106-15 Salem
Found CIM in good Condition 7"
deep in Crushed rock 109th Ave S.W.
The Corner Falls 5' West of ℄
109th Ave S.W and 3' North of fence
line East.
Bottle Cap in PP# 39194 East 38.60
spike & CSD in NW side 8" Burr oak S.W.
60.42'