8-27-69 set short C/M from Cemetery lot corner #651504 (1)

1/4 corner 15-22. Salem 106-15

~~No records~~ - Cemetery Record (Rivers. de Cem. 1870's RJ pony

Co Hwy Dept 6-1964 B285'-

assumed corner

Disc	power pole	NW	72.24
"	fence post	NE	68.69
"	Cor F post	SE	71.0
1968 cor FP SE & Disc			57.29
B post Fence P. "		NNE	88.23
Disc in oak Flume		SE	99.61
Oak NE Disc		NE	91.19

Mean N 26 41-82

8-27-69 JKerr carefully checked plat of Riverside Cemetery laid out by Perry in early 1870's found that 1/4 cor 15-22 was used and south edge of first alley from south boundry cemetery or 85 links or 56.1 was E-W 1/4 line and most westerly lot line 49.5' or 75 links from 1/4 corner. - found six lot markers on north side alley as south side in true line projected this line to center road 49.5' west of last lot marked then came 7 lks 4.62' south and set short C/M as corner. very near center of new road about .5' west and 4.5' ± south of county accepted corner

- disc in brace post of west cemetery fence NNE 91.63
- " " cor post " " " " " co 88.23
- which is post south gate closest against SE 55.24
- Co Geodetic bench Marker brass in SE bridge abutment center co 57.19

NNE 139.25

#651504 (2)

1/4 Corner 15-22 Salem 106-15
Set by Michael Karrick 6-1854
71.85 - Creek 18 lks wide runs SE and Enter timber bears N W
True line 40.00 Set quarter section post in mound with
trench pits, charred stake and Osage Orange
seeds NE & SW

(651504)

6-1-99
MW, RF, AE

(29)

1/4 Cor 15-22 106-15 Salem
found CIM in good condition 2"
deep in ℄ CR # 3 55 1/2 North
of South Cemetery fence
Set ReF pipe SE of Corner
49' East of ℄ CR # 3 and
21 South ℄ driveway South
side of Cemetery.
T@ ReF pipe
YRt Brass Disk in SE Corner
Bridge # 55515 to 1/4 Cor 15-22
339° 14' 40" 340° 29' 06"
0° 02' 54" 1° 17' 12"
339° 11' 46" 339° 11' 54"
To 1/4 Cor 15-22
VA 88° 16' 00"
Slope 104.285 Hor 104.235

To Brass Disk in Bridge # 55515
VA 89° 17' 56"
Slope 231.77 Hor 231.75

NO 447
NATIONAL PRINTAWAY