X 9-3-1974 Set Short CIN - over 5/8"x12" rod in Bit Road Surface (1)

1/4 corner 22-27 Salem 106-15. #652204

3-1878 Hunter P331 No 325 S 27 C Johnson & others.

found remains of old stake in center road in line of fence running west, aered by Mr. E Alvord who knew of corner since original homestead claim.

- set boulder stone 8x10x18 in place of stake.
- 16 east set temp stake N&L 19.99½ N 89°25' W
- 16 south set stake N&L 20.06½ (1324.29 N 35' E
- 16 center NE¼ 27 set stake intere lines (parties involved will set stone (1/16 above)

over)

1933 Co HD B 76 P2. found stone mon.
Sta 78+93.3 corner as PI Δ 0°07' right going N.
Meas south to Center 27 (as PI) 2642.3
Meas north to assumed point as Center 22 2618.4

1964 Co HD B 285 found pointed boulder.
left stone in place set 2"x2" wood hub near.
latest Co RPS.

Sp line in PP		NE	94.19
Hub	VOID	E	81.28
Hub		NE	73.60
Hub		SE	75.86

Meas north to center 22 assumed 2620.31
Meas south to center 27 as C/M 2643.47
rod near in subgrade (stone claimed still in place) see card #2.

Card #2 1/4 22-27 Salem 106-15 (2)

#LS2204

8-27-69 J Kell found nail in center road
- found hub RP east set by Co HD 81.28 set
½" rod in west side of 2x2 hub., field ridge, no fence.
- found disc in power pole NE 94.14.
- loop on top culv end flare clamp S. end field culv. SW 52.3
- " " " " " " N " " " NW 52.1
- lines fence west & center N-S road.

Must dig up this area to set C/M - prove corner from below

~~Corner disturbed - go to HOE - 6'N~~

3-17-72 Meas 1/4 22-27 nail S to Center C/M 2643.1

Elec Meas nail above East To C/M 22-23-26-27 R 2648.58
2642.88
R 2639.32

(over)

9-3-1974 Co. Surv.

Set CIM. over 5/8" rod in B.t. Surf Cored #3 - 2.3 E. of ℄
Set This Corner by Projecting line of S.1/4 Cor. 27
over Center 27 (a CIM on stones) and on E-W Section
line. This Corner now falls very close To Average line
of fences running East and West, but about 6 feet
short of T. Hunter's meas To Cor. 27 however, 1/16 fence South is
closer To Correct using our new Corner as set.

Dug hole here (actually about 3' N) and found that Co Hwy Dept.
had Subcut for road Grading and no chance of old Stone
still being here. (Shame on Co. Hwy Dept.)

R.P.: C.S.D. ⌀ side of PP # 11223 E.S.E 52.65'
Top lag nut N end 24" C.M.P. NE 43.50'
S.E Block corner house S.W 182.1'

#652204 (3)

1/4 Corner 22-27 Salem 106-15

Set by Michael Karrick 6-1854

27.00 Creek 5 lks wide runs NE, and enter Aspen brush

40.00 Set quarter sec iron post in mound with trench pits charred stake and Osage Orange seeds NE & SW

(652204)

5-28-99
MW, RF, MR

(27) 1/4 Cor 22-27 106-15 Salem

fd CIM in good Condition 3" deep
2 1/2' east of ℄ CR #3 in line
of Fences E & W

Set RefPipe east of Corner
51 1/2' East of ℄ CR #3 and
12' South of field drive

TC@ RefPipe

4R+ PK in PP #39711 (1st pole south
of Corner on East side CR #3
to 1/4 Cor 22-27

92°58'50"	93°34'22"
0°01'00"	0°36'36"
92°57'50"	92°57'46"

To 1/4 Cor 22-27
VA 88°51'44"
Slope 49.43 Hor 49.42

NO. 447
NATIONAL PRINTAWAY