#652504 (1)

1/4 corner 25-36 Salem 106-15

5-1873 Hunter P220 No 224 S36 H McDee, L Haskins
Peter Anderson

found remains of old mound with pieces of rotten stake in center. B tree tested 4.91 chs dist but bearing of S25°W was really S 73° W. no mention of replacing corner.

-1/16 west set perm stake N&L 20.01½.
-1/16 south set " stake N&L 20.04
-1/16 east set temp stake N&L 20.01
-1/16 center NW 1/4 set stake intersect lines
-1/16 " NE 1/4 " " " "

over

5-1873 Hunter P 222 no 225 S. 25 LA Holt, E Dwyer, L Hanson, M C. Donnald.

1/16 north set stake M & L 19.90

9-9-69. McGhie assist. - Meas west from fence south at NE 36 from rod accepted as true NE corner later. projected assumed fence line of N-S 1/16 line to fence on north line of E 1/2 S 36. Meas to this point 1320.5 exact record. Cont line west, meas only, found fence north at 2641.0 set long twisted 1/2" rod at base of rotted leaning corner post in exact line fence north. This could and should be accepted as true corner as fences were results of surveys. Meas south to C1/4 set 5253.6 a record measurement. No RPs.

(2)

#652504

1/4 Corner 25-36 Salem 106-15

Set by Michael Karrick 6-1854

40.00 Set quarter section post

Burr Oak 52 s W 491

Dug Trench

8-13-1980 (1980 Remon BK) 1/4 Cor 25-36 & Dug small hole on South side corner post to fenced North and East. Found soft spot - probable location of an old post. Drove a CIC on 4' tetapon at this location. Corner 1.7 SSE of present c.p. - Spike in West side of the corner post (survey marker sign on post) NW 1.71