/ 8-13-80 SLCIM

#653606 (1)

¼ corner 35-36 Salem 106-15.

5-1873 Hunter P220 no 224 S36 W Lee, L Haskins
Peter Anderson.

found stake in center road claimed by a Mr Nelson and others as where stake stood in mound before road opened. 10" burr oak S80°E 6 lks was govt notes but same tree bears S86°E 65 lks accepting fact some govt notes in error. stake in road nearly on line and within 2 lks of midway set stone 2 x 9 x 20 ~~lg~~ stake. being replaced by stone.

1/16 north & south set temp stakes M & L 20.02±

1/16 centers of NW & SW ¼s set stakes at inters lines.

1/16 east set stake M & L 19.99 to center (a stake).

11-3-69. McGhee assist

Meas from E-W fences at NW cor 36 found E-W fences at this corner at 2638.3 a very reasonable, acceptable, measurement. Corner may as well be set on line fences and in center road. Transit set up showed road center as straight likely on old center line.

- Center Twp road running east 1319.5.
- Nail set by County Hwy dept at 5279±

Set by Michael Karrick 6-1854

40.00 Set quarter section post

Black Oak 10 S 80 E 6

Dug trench

1/4 Corner 35-36 Salem 106-15 #653606 (2)

7-7-1980 (1980 Lemon BK) 1/4 Cr 35-36: Dug from t.n. 1½' West, 3½' East, 4' North, and 1½' South by 11" deep to clay (These measures taken at bottom of hole). Did not find anything even though there was ½' to 1' of black dirt left over clay. We then dug farther South appx 4' more but did not strike the stone and did not have time to scrape this area by hand.

t.n. } Spike S 10.78 Spike N 8.40

7-9-1980 (1980 Lemon. BK) 1/4 Cr 35-36: Dug another 3' off the West side of the hole dug 7-7-80 to be sure the road was well covered. Found nothing. Probed West wall of hole.

8-13-80 (1980 Lemon BK) 1/4 Cr 35-36: Set a CIM on a ½" x 18" iron. This corner set 4½ lks West of a straight line between the section corners as per T. Hunter's Survey No 224 (See Old Field BK) and at Hunter's prorated measure from

Sec. Cor. 25-26-35-36 (prorated against our measure from 1/4 Cor 25-26 to Sec. Cor. 25-26-35-36.)
RP's: CS Disc in pp #7313 West 49.75'
Corner is 1.5' South of fence E & W & 1.5' East of the ℄ Co. Rd. #15.

8-3-95 FOUND CIM 10" DEEP IN BLACK TOP CR #15

6-27-96 FOUND CIM 9" DEEP IN CR #15. SET REF PIPE ON DITCH SLOPE SSE OF CORNER 21'1/2' EAST OF ℄.

T@ REF PIPE
4RT P.K. IN PP# D15-35-10.0 TO 1/4 COR
152° 32' 06"
TO 1/4 COR 98.14
CHD DISK IN PP # D15-35-11.0 WNW 49.70

REMOVED CIM
6-27-96

10-24-96
CHD SET 1" SA
PIPE W/CAP