1

6-24-77 CIC

#710206 #1

1/4 corner 2-3 Quincy 10 7-11.

See field BK 9 p 41-67 468-79 + p 81-82

10 & 11 - 1900 W Fraser P 692-8 no 615 d 2-3 9 Parties
10-11 see NE 2.

as "D" P 693 - corner gone for years, no one knew anything about it, no evidence available to relocation.

set iron ~~stake~~ post 40" long with bur at bottom and marked stake by side ~~M & L~~ Govt Notes in field book according to description but Plat shows govt proportions as follows - south 19.92 - 1992.

north 19.92 - 1942.

1/16 east "19" iron stake driven M & L 19.97 1/4.

1/16 north "5" drone stake ~~quoted as M & L~~ according to Govt notes but Plat shows govt proportions of 19.92 then 19.42 on to corner. Also set Stone

1/16 south "7" drone iron bolt M & L 19.92 3" Beak 1314.72 S 20° E 12 lks 7.92 1284.72 1314.72. 2" aspen 2 W 9 lks S 20° W 5 1/4 (Fraser)

other corners intermediate see Center 2 plat on reverse card

6-24-77 Found corner found by DNR - a 1¼" pipe over a 40" bolt with a nut on the bottom (removed) Set a CIC/p² as the corner. (Corner is 16' West of water's edge (Whitewater River). Set a steel fence post on the N side of the CIC.

RP's: Spike in S side blazed 7" Box Elder NW 5.05
Spike in W side blazed 9" Box Elder N 20.48
Spike in SW side 28" blazed Cottonwood NW 67.8.0
Spike in E side blazed 9" Box Elder SW 16.10
Spike in E side blazed 9" Box Elder SSW 95.5

1/16th N 6-24-77 dug 4'x4' to clay at a point on line from SW 2 over 1/1 Cor 2-3 and at Will Fraser's measure from ¼ Cor 2-3 but found nothing.

1/4 CORNER 2-3 QUINCY 107-11 #7102060 #2

GOV NOTES 1855 W.M. A JONES

SET 1/4 SECTION CORNER post 40chs NORTH of 2 3-10-11

TOTAL MILE 79 50 5247.0 N 1/2 2607.0

CORNER CAME IN STREAM SET WITNESS STAKE 47 LKS E 31'

18" ELM S 30E 47 LKS 31

12 LINDEN N 85E 39 LKS 25.4

CORNER DOES APPEAR to come IN WHITE WATER RIVER