#713104 (1)

X

1/4 corner south 1/4 31 Quincy 107-11
north 1/4 6 Doner 106-11

10-1874 Hunter P262 no 261 S31 Peter Scherer etal
found stone planted center road claimed set at 1/4 stake.
1324.7
1/16 east - found stone correct within link left 20.07 1/4 N & L.
1/16 north - set stone 5x5x25 20.10 1/4 N & L. 1326.96
1/16 west set stone 3 x 3/12 x 22 line & propdist. 19.90 chen 19.49 1/4 to turp cor.
1313.4 1286.9
39.39 1/4 - 2599.9

8-1887 Hunter P419 no 408 S6 J Kelchum, W Miller
corner missing, projected line & doubled distance from
NE 6 ones 1/16 cor, set stake, dep, Mr Scherer will set stone.
1/16 E found stone P262 - 1/64 west set stake 9.95 on line w/spec cor (1/16)

Co Hwy Dept B146 P58 1943.

½" rod in road. 2597.67 east of Hwy Co record.

some discrepancy in meas from N¼ west – Got Records from B262 Hunter P421

County 39.358 chs.
Hunter P262 39.395 "
Hunter P419 39.80 "

(Result Project line in from North of parcel.

set above rod on transit betw section corners & line 43

on prop meas.	5244.8	2597.67 – W	2647.13 E
	R 5249.5	R 2599.9	R 2649.6
Rec m	PP	S.W.	53.58
" "	Cor FP	S.E.	41.12
east side of power pole		S.W.	74.88 corrected R.P.
– angle west to north		90°16'	

Gov't notes: Sept. 1853 Set Post & drove charred stake built mound with trench

See Card 2

Card #2 S 1/4 31 Quincy 107-11
N 1/4 6 Dover 106-11

#713104 (2)

5-25-73. found iron rod used by Co H D (origin unknown) dug with air hammer, road cut to bed rock. where corner should be - 1/16 fence North/running east - meas S 1/2 W 1/2 31 ac West side 2641.39 - N S 1/16 line 2646.35 or 4.96 diff which would make east side of SW 1/4 31 2646.35 + 9.92 or 2656.27 R 2653.52 R W side 2643.3 R Mean 1/16 2648.41 - dug with air hammer large hole at 1/16 north to search for recorded stone 5 x 5 x 25 but road gone. on running aerial from 1/16 corner west line felt well in hole dug set working - 16 W set iron where stone (lying flat) and dark tobin clay. indicated stone might have been at one time.

(over

Corner last could replace from North and west lines.
as center could be set from west. See center 31.

4-17-79 Shot 1/16th West

5-9-1979 At S. 1/4 Cn 31: We set a CIC in telepan at the intersection of the line from the SW Cn 31 over the 1/16th Cor and the N-S 1/4 line of Section 31. The corner corner 1.42 West and .17 South of our traverse iron (removed) The corner is 1½' South of the South edge of the blacktop, in line with the ℄ of the road north, and 13' South of the ℄ Co Rd 9

RPs: CSD SE side power pole SW 39.18
CSD NE side corner post SE 76.30
Spike and CSD E. side 16" Burr Oak SSW 95.87

South 1/4 31 107-11 Quincy
North 1/4 6 107-11 Dover

#'11'104 (3)

6-10-93 CHD Took grading ties to CIC/P² before Construction of CSAH # 9

12-20-93 CHD Set 5/8" Iron as Corner in Crushed Rock CSAH #9

11-29-94 CHD Set 3/4" Copper Rod in Concrete CSAH # 9 as final Corner. The Corner now falls in ℄ of CSAH #9