/ Set 1"x20" pipe Flush with road surface (1)
10-24-74

#713109

1/4 Corner Center 31 Quincy 10 7-11

10-1874 Hunter P262 No 261 & 31 Piles Scheer etal.

set stake at true inters lines

1315.05 1310.76

1/16 - west - set stone 2x4x25 on line 19.92½ then 1986 to 1/4 cor

1/16 north - set stone 2x8x12 19.96¼ M&L 1317.52

1/16 east - set stone 2½x6x25 19.98 M&L 1318.68

1/16 south - set stone 5x5x25 20.10¼ M&L 1326.76

1/16 stone center NW¼ 31 3x8x15 at true inters lines

1/16 stone center SW¼ 31 4x6x18 at true inters lines

1945 B 146 P58 corner not established

Mnac. ¼ 30-31 stone found south to true S¼ 31 5271.9

Cover

5-25 & 30-1973 set nail in center road in exact line fence running west - meas elec L. 2638.62 to county rod. R. 2653.52
1/16 fence E (not in orig survey as no fence west) came 1307.08 from center nail and 1331.54 to county rod. should have been 1326.76 each. - dug for 5x5x25 recorded stone at 1/16 south of center and found road cut and gone. dug at proper mags and also at inters of line from west over 1/16 stones. which came in same area. found nothing.
- easily found 1/16 stone east of center. 2½x6x25 2' deep. about 1.6' N of new corner post in roots of willow 2.3 SE to head of 20 ø nail on SW side wood cor P. 13.18 WSW to edge new green steel corner post.
at very near recorded distance as meas on ③ to fence 46' S.
See Card 2.

Card # 2 Center 31 Quincy 107-11 #713109 (2)
also found positive recorded corner at E 1/4 31
also found positive recorded 1/16 stone 2 x 4 x 25" west
and 1/4 stone W 1/4 31 & E 1/4 36 Viola.
Meas W 1/4 31 to 1/16 stone elect - 1310.21.
Meas above stone to nail in center road. Co # 7. 1314.39
indicating Center 31 west of center road.
40° offset line from west came. south of .00 nail
Corner can easily be reset from E or W —
4-17-1977 Found the pipe at Center 31 and the
iron at the 1/16th North in good condition

10-24-1974 1/16th North Dug and found bottom 6" of recorded stone 12" deep in ℄ of C.R. #7 and in line with the fence East. Drove a 5/8" x 12" rod over the stone and flush with the road surface.

RP's: Bottle cap S side corner post East 40.11
Punch hole S end 18" C.M.P ESE 29.79
Bottle cap S.E side PP # 680 SW 44.83

10-24-74 - Cente 31 Dug with the tractor 3' deep and found a piece of limestone 2"x 4"x 6" down into clay. We accepted this as the corner because it is within a couple tenths of being on the E-W 1/4 line subject to remonumenting the line. Drove a 1"x 20" pipe at the corner flush with the road surface ℄ C.R. #7

R.P's Punch hole S. end 18" Field tube C.M.P SW 38.6 OK
Punch hole N end 18" Culvert C.M.P SE 43.6
CSD N side corner post WNW 57.35

Corner fall in ℄ of CR #7 and 8' ± South of the fence running West.