#713204

1/4 corner south 1/4 32 Quincy 107-11.
North 1/4 5 Dover 106-11

9-1929. Co H D B 48 P 27 assumed corner.
Blazed tree S 32.3
SW corner south headwall culv SW 12.8

B94 P46 re recognition of corner 1938 fence south at sta. 158+20 F E, W, S 38' S - Sec cor mea 131+80.15 or 2639.25' then to sta 184+64.35' or 5283.6 for Mile

4.3-70 Co saw no apparent sign of where corner could be except boundry fence south

Gov't notes: Sept 1853
Set Post & drove charred Stake built mound with trench
10/23/92 County Surveyor dug with backhoe
for gov't corner at M & L between section
corners. There was 6" of blacktop on C.R. 9.
We dug 5½' deep to clay there was 3'
of black dirt below oldest road. a
stake could never have reached clay it
was probably gone in road const.

June 1993 CHD Took grading ties to M & L position
of ¼ Corner before Construction of CSAH #9
12-10-93 CHD set 3/4" Iron as Corner in Crushed
Rock CSAH #9
11-29-94 CHD Set 3/4" Copper Rod in Concrete
CSAH #9 as Final Corner @ M & L Position
Between Section Corners