X 11-29-94. 3/4" Copper Rod set as Final Corner in Concrete Ck. #9 @ M&L Location Card #1

#723604

1/4 corner south 1/4 36 Vola 10 7-12

North 1/4 1 Eyota 10 6-12.

6-1893 H Fraser P 517 No 483 & 36 Urban, Beck, Quimby

Corner gone, no evidence, B trees or knowledge of corner.

set stone 2½ x 8 x 25 M & L. 39.85 S 89°38'E

1/16 north set stone Must be "3" M&L 20.00 2630.1

this corner either stone 2x8x16

or 2 stones 2x9x15 and 2x9x12 } Not numbered on plat.

(over)

1938 Co Hwy Dept B94 P3 Corner to P.I. ∠ 0° 8' Rt from E
found limestone with "2" x 6"" top 1/2 stake on west side
AH 24" oak NW 24.6
Lp 8" tree trunk NE } Sole cross 89.58 (84.55 ?
" 13" " trunk NNE } sole add. 81.7 Fraction 22.7 Fraction 27.3
9-1927 Co H.D. B48 P33 stone in place. R 2630.1
24" oak NW 25.9 — 10" oak NNE 22.8

1935 Co H.D. B75 P63 found L & 2"x6"x? in mound
set 8"D on West side stone, cut cross, 2"x2"x18" on west side.
Spin 24" oak NW 26.6 - 8"D in same tree 25.4 Take.
Reckon F.P. N 36.4

1/4 Corner South 1/4 36 107-12 Viola Card #2
#723604
North 1/4 1 106-12 Eyota

From Section work in 36 & 1 in 1992
Survey we determined W. Fraser M&L
Location best fit Existing Property &
Monumetation This area in deep I 20 Cut
to be worse after grading of CR#9 in 1993

11-30-93 CHD set 3/8" Iron in Crushed Rock
CR#9 after Construction

11-29-94 CHD set 3/4" Copper Rod in Concrete
CSAH#9 as final Corner @ M&L Location