1. 5-14-69 set CIM one 1" x 18" rod MLL 2618.3 (1)
reset dsm. 5-1-79 over trap for Came back on my N. 1/16 corner 1979
1/4 Corner 16-17 Haverhill 107-13
5-1894 2+ Fraser P549 No 507 SM Robinson #731606
John Mahon.

Could not find corner. set stake & stone
M&L 39.75 2623.5'
-16 North set stake M&L. 19.87 1/2. 1311.75
-16 south " " " " "

Corner seems to be gone unless it lies where one least suspects - McGhie set rod as assumed corner.
8-17-1966 Marr found McGhie rod dug for true corner.
run line direct from CIM SE 17 to heavy corner post center at area of 1/16 corner north of E 1/4 17, mine carefully north to road at E 1/4 17. set 120 D at 1/16 past south of E 1/4 17 line came 1.3 west of 120 D at 1314.35 1311.75 offset 15' west continued N.
- over -

at 1/64 corner south of E 1/4 17 found Mc Ghie rod, at came 650.9 from 120 D at 1/16 or 1965.25 R 1967.63.

line as run came 17.64' east of rod set by Mc Ghie as 33' west. - Cont north set nail in E road bon 15' E at 1305.45 or total C/M to center road 2619.8 R 2623.5

- set 120 D on 15' E at 1314.35 or 2628.7 on north edge road. as tie up. which lies 4.40' SW to center PP and 20.0' NE to SE corner RR tie corner post.

Mc Ghie rod near center road on line fence north.

Caption in pencil on P 549. 9-1901 by W Fraser.

set 1/16 stone & stake N & L west 20.03 1/2. 1322.31

" " stake " west of SE 17. 19.97 1318.02

set occasional stakes on N-S 1/16 line for fencing.

#731606a (2)

Card No 2 1/4 16-17 Haverhill 107-13

5-1969. J Carr. B98 P58.

finished running Section line between 16-17.

total mile 5236.6 (1"x18" solidrock.)

Set C.I.M. ~~wrong~~ over rod glass at 2618.3.

- 1/16 fence north running west from N E 17. 1311. ±
- 1/16 fence south running east from S E 17. (Bryant Ranch) 13.14.35 ±
- Nail (McGhee) in power pole. SW ~~4.2~~ 48.08 (1974 R.P.S.)
- ~~"~~ " ~~in stob~~ " gave W N W 63.4
- " " in R.R. tie or post. 3' W & N ~~2.11~~ 23.74

Iris center E-W road. - near line Main fence north away from road.

1970 believe McGhee rod near exact M & L, Helena C.I.M. set there. (Lee)

5-1-74 Reset C.I.M. over true stone (vert. limestone), stake + boulder on top of all.
Reset a 1"x24" rod between stake + limestone + set C.I.M. Cor. came 1.0' N. + 0.4' E. of J.K. C.I.M.
Cor. falls 1.0' E. line to North. + 1.0' South & road.
R.P's
Nail S.E. side P.P.# 34317 S.W. 48.08
Nail E. side R.R. tie. Cor. post N. 23.74 (Possibly gone 1977
Govt Notes W.B. 1/4 bk 1853
10.00 Std ⊥ Std post ⊥ foot of h. //
Bur Oak 9.0 W 70 W 49 1/4S
Bur Oak 10.0 S 58 E 75 1/4S
9/22/89 FD CIM PP# 34317 GONE, CHECKED TIE TO RR TIE COR. POST
50.84' SW TO CSD IN PP# Q6077