#732209

9-2-1965 C/M re-set by County after grading.

1/4 corner. Center 22. Haverhill 107-13.

5-1875 Hunter P273 No 271 S 22 P Quinlan found stone boulder anered as corner as set by J V Daniels, surveyor, tested by E-W 1/4 line and proved exact so did not test other way.

-16 north set stake M & L 19.92½. N16°E

bearing of line E & W S 89°40'E

---

stone found in road set C/M over stone and stake. in 10-24-1963.

Co Hwy Dept in grading road on new curve - over.

removed corner which now comes in east ditch of new road. County set C/M in place old corner.

Lg	Maple.	SW	48.32
Lg	power pole.	NW	50.85
"	corner post	E	32.86
	brace pole	NE	39.50
Dice	fence post. (new RR Tie	NE	45.43

other old RPs gone. like tree & brace pole.
Corner lies nearly in bottom of east road ditch.

1923 C.H.D. Book #31 Page 26 Found stone

7/31/69 FD CIM IN EAST ROAD DITCH

(3) 2-11-11

"732209"C CENTER 22 HAVERHILL 107-13

FOUND CIM IN GOOD CONDITION DOWN 0.5' IN EAST ROAD DITCH. CORNER FALLS 29' ENE OF ℄ CR # 11 ON CURVE.

DISC IN FENCE POST (NEW R.R. TIE) NE 45.43'

CSO IN PP # 22986 NNW 99.68'

SPIKE IN CP EAST STILL THERE BUT 12" PINE TREE ON LINE

OTHER RP'S ARE GONE.