X 1989 FD [redacted] (3/4" PIPE) #733204 (1)

1/4 corner South 1/4 32 Haverhill 107-13
North 1/4 5 Marion 106-13

6-1899 W Fraser. P658 No 586 & 32. State of Minn. found old stake in center road, set stone. 2x8x26 ins to place., 49 lks south of line of trees on N side of road and. 12 lks east of a line with west side of barn north of road.
-16 west set stake 33' north of M & L 19.84 1/2 =
-Meas east 40.01. No stone found. 1309.77 2

See T. Hunter Bk 5 p.43 3-1978 Sec. 32 Haverhill
at "F" found old Stake in Center of Road Set Stone in its place 22x6x5 with broken Stone around Bottom.

-over-

Corner found & used many years. iron bar riser in place. over stone - corner likely fairly deep under tar road. trace in north end large culvert. NE 44.0
" " south " " " " SE 52.0.
Drawn End PP 1910
Center punch ~~mark in cornet post~~ 17.2 N ? SE ? ~~45.0~~
NW 42.2 S-

6-1969. J Kerr referenced corner as road would be cut there over 6' for new road.
found spud on road - set transit on spud with ax on NW northeast
Corner basement blocks of house east of corner (red blocks).
set rod at 100' then 67.75 on to house corner. 10-27-72 Found PP
- rod to SW corner step platform (house) NW 53.8

Co H D. B 277 P2.
2634.69 west to S 31-32. south - 2619.50 w.c.r
2640.87 east to S 32-33 south SW Post Rec 97.5-8 PP

Card # 2 South ¼ 32 Haverhill 107-13. (2)
North ¼ 5 Marion 106-13.
#733204

1937 Co. Hwy Dept B88 P.2.
Corner limestone and ¾" drill rod Sta 52+62.8 PI RT 1° 4'
from assumed spike at S¼ 31 assumed.
P2 RPS. Sp 15" Maple NE 66.6 – Sp tab brace pole NW 44.2
Sp 24" oak SW 98.8
P15 RPS. Sp (bent) 18" Maple NE 66.6 - Sp Dist P Pole 41.2 N.W.
Sp Dist Tel pole. SW 47.3 Sp Dist P Pole 64.7 S S W.
record betw True corners S¼ 31 and S¼ 32 2630.76 + 2619.54
M 5250.3 Thos Fraser & Hattie both 2630.76 S¼ 31 to S 31-32.
Wm Fraser position 2619.54 or 19.84 ½ (1309.77 M & L.

NOTE: This Corner Location confusing, but probably not Correct as it is shown. Corner Should Probably go where it is. W.C.F. time.

over Topo

S ¼ 31 assumed as .00 - Note fd S ¼ Cor. 31 5-16-1974
S 31-32 no corner but 26 + 30 fence RT 22' true 66'

12-1978 Co. Surv. RWB research
After analyzing the Co. Hwy Dept. data in field Books #88 & #186 and checking in J. Kerr's field book notes, I came To the conclusion that the current position used as this ¼ Corner is probably not the W. Fraser Corner as his Corner should be about 4' North and 7' West of the current position. however, there is some confusion between W. Fraser and T. Hunter and possibly the current position could be T. Hunter's stone, we will dig later To determine if either W. F. or T. H. stones are still in place

Oct, 1857 John Fellows Pg 41 No. 63 shows ¼ East with Meas. 19.67 chs East to So. 32-33

1/4 corner Found 1/2" Rebar 1.1' Deep

Witness 1/2" Rebar 100.5 #733204

(5)

Gone Home.

10.00 Set pin & steel shaft with yellow plastic cap. Both found and Found Pins set DE Orig. Orig. NE Both Orig.

11-1983 Vince Fangman took RP's to convert nail in ℄ CR 9 and 17.0' E of ℄ Rd South. Vince measured 2627.49 West to S.31-32.

Nail & Disc in PP NW ~~56.05~~

Nail & Disc in PP SE ~~68.76~~

Nail & Disc in PP SW ~~85.53~~

11-1983 V.F. set 3/4" Pipe at P.K. Nail location as Final Corner.

1989 FD 3/4" P. PE 11.8 ~~DEEP~~ SOUTH TO ℄ OF C.R. # 9

16.5 WEST TO ℄ OF C.R. 109

42.28' NW TO CHD DISC IN PP # 19110

78.89' SE TO CHD DISC IN PP # 47210

1965 CHD set spike with punch mark in center
(assumed corner) Rps spike in P.P. NW 92.52' (book 305)
spike in T.P. SW 54.4'