6-27-1977 Set C.I.M. over W. Fraser Stone

9-13-1965 set CIM over orig rod & 1"x 16" pipe.

4-29-76 a.g. found ½" rod - set a CIM.

section corner south 31-32 Haverhill 107-13

7-16-76 found W.F. Stone.

6-27-77 set CIM North 5-6 Marion 106-13

#733205

5-1891 Chas Fraser P457 no 441 L31 Stab Minn.

Corner gone - reset stake from B tree standing C.L.E.

Came in line fence south, stake in place when line run north.

- Meas west 39.86 2630.76' then 38.56½ to Surp corner

2565.29

6-1896 Hunter P603 no 548 L6 W Hulburt

corner gone, replaced L E B T. J Coe, W Bracken-

corner came in line fence south. 1915.38. 2541.96. ridge.

-16 west set temp stake N & L 19.93 - 38.56 N'ly 6 to

-over- NW 6.

6-1899- H Fraser P 658 No 586 & 32. Stab Mon.
found stake tested L.E.B.T. in north track highway.
set stone 2x7x16 by side of stake.
-16 east set stake 33' north of M & L 19.84½.
1309.77

---

corner found and pipe placed as corner or riser
9-1965. found pipe Kerr's cert says ½" rod 40" below black top road.
2' south of north edge black top surface.
set C/M over 1"x96" riser over orig pipe.

Dist to NE side	tel cable pole		LE	83.45
Dist LE "	" " "		SW	94.6.
Dist LE "	power "		NE	50.6.
Dist NE "	24" Hazel burr oak.		LE	96.0 21.84
Dist SE "	Power pole		NE	48.86

(2)

Section cor. South 31-32 Haverhill (107-13) #733005
North 5-6 Marion (106-13)

4-29-74 Dug with the compressor - found a ½" rod + C.H.D spikes - the C.I.M. had been destroyed or removed. Dug around for evidence of the stone but found nothing Reset a C.I.M. over the ½" rod + accepted the corner location.

R.P.'s

over

Note: orig B.T. S 14°E 12" Bx A 134 lks = S 168 E

T. Hunter Bk 5 p. 43 3-1878 Sec. 32 evidently used corner but did not identify what was used.

7-16-76 Dug with backhoe on line and measure from SW 31 also 5¼ 31. Found remains of W.F. stone (2" x 7" x 9") with stake on N. side 2.7' deep. Set 120d on S. side of stone and iron on N. side of stone. Corner 4.75 and 6.8 E of CIM previously set at Kerr's location and .45 N and 1.35 E of tranne nail. Set ½" x 24" rod to retain location

7-1979 Shot corner in control survey / 1979 Remon. Blk. Page 103)

6-27-77 Set C.I.M. over W. Fraser's stone with Chrome pieces above stone

R P's C.H.D. disc in P.P. # 9124 N.E. 63.19

C.H.D. disc in light pole N.W. 82.81

Corner falls 5½' South of F & West bound Lane Co. Rd #9

" " 17.4' North of north edge curb on median

(5

#733205

Gold Mine,

Sec. 31 T. 5 S. R. 11 E. of Salt Lake

Sec. 5 T. 6 S. R. 10 E.

Gold Mine,

Sec. 31 T. 5 S. R. 11 E. of Salt Lake

B. C. 14 N 65° W 19

B. C. 10 N 65° E 55

B. C. 8 S 75° W 16

B. C. 12 S 14° E 124

"733205 F S SEC COR 31-32 HAVERHILL 2-17-99 EPA JFJ BB
N SEC COR 5-6 MARION
FOUND CIM WITH HEAD BROKEN OFF DOWN 0.5' IN
BLACKTOP CR #9. CORNER FALLS 5½' S OF ℄ WBL
CR #9, 17.4' N OF NORTH FACE OF MEDIAN CURB.
60.1' ENE OF ℄ NBL OF CSAH #22 ON CURVE.