#741105 (1)

9-11-1963. set C/M over pipe & junk.

Note: March 1977 Corner now under B.T. Surf Road.

section corner 10-11-14-15 Cascade. 107-14
4-1870 R Perry P108 no 147 & 9 & 10 M. clark.
corner "D" "Established this point on statement of two
& Mr. Slagus Lone, Mr Boardman & Mr. Josenger,
and from appearence their statements are correct,
and set a stone as section corner.

Meas west to point found 40.03 (2642.0

6-1874 Hunter P256 no 256 & 10 Philo Boardman.
Corner not mentioned or described only that
1/16 N set stake M & L. 19.73½. 1302.51. and
1/16 W set stake M & L 20.05 1323.30. Cont.
ner.

also 1/16 stake set in Center of E 1/4 10 at inters lines
2-1878 Hunter P 329. No 323. S 14. R Elliot, etal.
Corner completely gone. Mr Philo Boardman avers that
the first post of his post and rail fence running
east on south side of road exactly opposite corner
when it was standing in mound and pits.
- also measured west to property corner set in Hunter
survey 1861 for line between Boardman and Hacket
as meas 15 chains. (9.90' which came within
2 lks (1.32'
- also meas north to stone at 1/4 10-11. 39.47 (2605.02
set stone 2x6x16 deep with stone 2x6x16 on top.
- meas south to temp M&L point 20.01 (320.66 40.02 (2641.32

Card # 2. 10-11-14-15 Cascade. 10.7-14. (2)

12-28-72 found CIM down about 6" in ~~dirt~~ crushed rock top road. placed. 60 D nail on SW side 16" butternut at 46.0 NW.
" " " " SE " 12" pine tree at 39.75 NE.
butternut N 29.0 still in place but now dead
corner pine 8.0' east of eye pine of west side house north.
- found 1/16 rod west set by J Kerr M & L 1317.67
in 1967 B93 P13. still within 1" of rod top
in 11-1916 B252 B this mear M & L 1319.5 to large limestone.
1/16 west side 22' E of fence N and 3' N center road.
New RPS 1/16. 43.0 NW to Top cap. on SW side cross cor post for N
60.2 SW to code nail in top 4" wood line fence brace post.

1-3-73 found 1935 Co HD cottonwood still standing and checked with CIM. - rod set west at 1/16 corners. on perfect line to 1/4 10-15

See Card # 3.

8-1958 J Kerr B73 P77. Geo Hagen survey.
found corner. and used for line east (no corner desc. (2)
- set 1/16 corner east a 3/4" pipe M & L. 1316.24 to.
buggy axle corner at Boldwins house corner. #741105
1/16 corner pipe 115.5 N W to S E corner house foundation (burned down later.
50. S W to 120 D in 3' triple elm tree.
also set 120 D on section line at 1520' from west.

9-1963. set C/M over pipe in place as corner and junk.
~~12-25-72 this corner should be dug up & checked origin pipe in?~~
83.65 8' W & N to S W corner old house foundation.
corner several feet north of center road (other RPS over).
-16 west set rod. M & L. 1317.67 See over for RPS.

7-1935 C & HD B75 P34 found. stone mon with bucks & glass.
83.6 N to S W corner house - 94.7 N W to twin cottonwood.
1-3-73 both these RPs still in place and same as C/M. corner now reflected correct over

#741105

Card # 3 10-11-14-15 Cascade 107-14 (3)

1-3-73 Con't- Meas line elect-weld found pointing indication of rod set by JKerr 10-24-68 at 988.26. =½" rod down 8" in new B.T. road surf.-set 1" pipe over it flush.- 9-9-1977 RB

west of SW10 and 1649.09 from S¼10. as prop line cor. for. line south to similar point set betw SE15 and S¼15- book 101 P 22. - Elec meas to strong mag indication 988±.

Meas E¼SE10 To ¼10-15. 2635.32

Perry. 2642.0. Hunter 1874. 2646.6. Co H.D. 1935. 2637.5

JKerr. 1916. 2639.0. JKerr 1968. 2635.35.

Meas El. ¼10-15 to PK at SW10. 2631.93 (PK not where JKerr used.)

PK at SW 10 Corner go 1.38 west see Card 3. (9-10-15-16.)

which would make Meas west 2635.32 and ~~2633.31 To S.W.10~~ 2631.80

analysis of this corner would indicate that corner location is the perpetuation of the orig. Corner. R.B.

Gov'T notes: June 1853 M. Karrick Deputy Surv.
80 chs. Set Post for Corner - Erected mound with
Trench pitts charred stake and osage orange seeds at
each angle.
at 62.00 chs. from south - Creek 8 lks wide runs East

4-1900 R. Fraser Sec. 14 Field BK 15 P. 45-48
used something as Corner and Took References
Corner of House N 34½ W 140½ lks
S 28½° W 43 lks Elm Tree (no size given)
9/27/89 FD 5/8" PIPE/CAP # 11622 RP's
4.5' SOUTH TO ℄ OF RD.
CHECKED TIE TO PINE TREE NE OK
BUTTERNUT NW, NAIL MUST BE GROWN OVER
FD 1" PIPE ± 988' WEST

(8)

4-13-99
GPA JPJ DB

"741105"

FD 5/8" PIPE/CAP IN GOOD CONDITION.
SET @ 1" SA PIPE/CAP AS REF. 7' in Line of P.P.
124.60' East of P.P. #

T@ REF PIPE
ART GRAM TO 741105
92° 44' 37" dhol 95° 16' 37" dhol
0° 04' 23" dhoB 02° 36' 25" dhoz
92° 40' 14" 92° 40' 12"

TO GRAM (CITY PT - 1" SA PIPE/CAP)
VA 87° 31' 50" dvoz
SLOPE 837.82 HOR 837.04

TO "741105" 255.1303
VA 86° 46' 46" dvo4
SLOPE 121.295 HOR 121.105

36.9129

"741105" SEC COR 10-11-14-15 CASCADE 11-9-99 LPA BTB RF
SURVEY CREW SET 120d SPIKE IN MEDIAN
OF 95TH ST NW FROM TIE OUT MADE IN APRIL.